

Product Change Notice

Issue Date: September 23, 2019

Change Type:

Add ASE Taiwan as Bump supplier

Parts Affected:

BCM88470CB0IFSGB
BCM88470CB0KFSBG
BCM88471CB0IFSGB
BCM88471CB0KFSBG
BCM88476CB0KFSBG

Description and Extent of Change:

Additional CuP Bump supplier - ASE TAIWAN


Reasons for Change:

- Adding bump supplier. Broadcom reserves the right to manage supplier.
- The construction of the bump is identical
- SPIL Taiwan has internally qualified the direct CuP bumping and in volume production.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The device specification will remain the same, which will ensure product electrical performance remains the same. Appropriate electrical characterization and reliability qualification will be performed on representative products to insure normal parametric distribution, consistent electrical performance, and reliability.

Box label will be changed to identify correct bump supplier:



ITEM DESC:
(1P)P/N: BCM53724B0KPBG
LOT: 525819901
Wafer Lot: CTB2345678
RoHS Compliant : Halogen Free

(9D)DC: 1529
(Q)QTY: 101
MAX TEMP: 260c
2LI CAT:

COO: CN
Seal Date: 13-JUL-2015
MSL: 3

INN_GEN(150058)
Fab/Bump: CT

Fab/Bump: CT

*Bump code will be updated to reflect supplier change

Effective Date of Change:

Product shipments using this change will be effective 90 days from the issue date.



Qualification Data:

| Bump Type | OSAT | Bump Supplier | Package Type | MSL3 | HTSL 150C 1000 Hours | TCT Cond B 1000 Cycles | UHAST 96 Hours |
|-----------|------------|---------------|--------------|------|-------------------------|---------------------------|-------------------|
| CuP | ASE TAIWAN | ASE TAIWAN | FCBGA+HS | PASS | 0/77 | 0/77 | 0/77 |

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.