


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350°C, 100 Watt max. and use a pencil tip.
- 4. Apply some solder to the solder tip of the soldering iron.
- 5. Put tip to wire in solder cup.
- 6. After 1 second bring in solder.
- 7. Heat for 5 seconds longer. Do not heat contact more than 6 seconds in total.
- 8. Remove soldering iron.
- 9. Wait until solder gets rigid again.
- 10. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



T nbH	HAND					tolerance			scale: 4:1
ED OR AAY NOT Y WITHOUT CONEC GMbH									material: SEE SHEET 1
	ВУ							dim. in mn	
	9						date	name	title:
E COP AND I PART	DRAWING					drawn	01.10.2015	Lehmenkühle	RECOMMENDED PANEL CUT-OUT
/ NOT BE COP // WAY, AND I A THIRD PART ON. OPYRIGHT OF	T ALTER CAD					appd.	07.01.2016	Fischer	D-SUB COMBINATION FEMALE 2W2CS SOLDER C
AY NG ANY V O A TH SION.						norm			with open 4-40 UNC thread
NG MA N IN A NN TO RMISS						d-old			dwg no: DIN-
MIN CED D OF IP A								15K1A1711	
DRA ODU SSE TEN ERSH		а	Original					Y	sh:
THIS DRA REPRODU BE PASSI WRITTEN OWNERS		rev.	description	date	name			11-6	part no: SEE SHEET 1

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

CONEC: 15-006793