


## Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350°C, 100 Watt max. and use a pencil tip.
- 4. Apply some solder to the solder tip of the soldering iron.
- 5. Put tip to wire in solder cup.
- 6. After 1 second bring in solder.
- 7. Heat for 5 seconds longer. Do not heat contact more than 6 seconds in total.
- 8. Remove soldering iron.
- 9. Wait until solder gets rigid again.
- 10. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

## RECOMMENDED PANEL CUT-OUT



	ED OR AY NOT WITHOUT	HAND						tolerance		7 \$	scale:	3:1			
										T 1	material:	SI	EE SHEET 1		
	NITH ONE	ВҮ							di	m. in mm					
	OT BE COPIE  VAY, AND M  IIRD PARTY  RIGHT OF C	NG						date		name	title:				
		DRAWING					drawn	25.03.14	S	Schmidt		PANEL C	CUT-OUT	-	
							appd.	25.03.14	Lehi	menkühler	D-SUB COMB. MALE 8W8P SOL			DER C	UP
	ANY V ANY V O A TI SION COP	CAD					norm	25.03.14 Lehmenküh			with hexlocking screw				
	WING MAY NC CED IN ANY W D ON TO A TH PERMISSION. IIP AND COPY	TER (					d-old				dwg no:				DIN-
	THIS DRAWING M REPRODUCED IN BE PASSED ON TO WRITTEN PERMIS	DO NOT ALT								<b>8</b>	151/1/1	164		A3	
			а	Original			CON							sh: 2	
			rev.	description	date	name	7		٦,		part no:	SEE SI	HEET 1		
			D	•	$\Lambda$		C	•			В			Α	

F

## **Mouser Electronics**

**Authorized Distributor** 

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

CONEC: 15-001653