


## Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350°C, 100 Watt max. and use a pencil tip.
- 4. Apply some solder to the solder tip of the soldering iron.
- 5. Put tip to wire in solder cup.
- 6. After 1 second bring in solder.
- 7. Heat for 5 seconds longer. Do not heat contact more than 6 seconds in total.
- 8. Remove soldering iron.
- 9. Wait until solder gets rigid again.
- 10. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

## RECOMMENDED PANEL CUT-OUT



	PIED OR MAY NOT TY WITHOUT F CONEC GMbH	HAND						tolerance			scale: 4:1	
											material: SEE SHEET 1	
	MAY NOT Y WITHC	BY							dim. i	n mm	1	
	COPIED IND MAY ARTY WJ	N.G						date	nam	e	title:	
	E COPIE AND M. PARTY TT OF C	DRAWING					drawn	15.09.2015	Lehmen	kühler	RECOMMENDED PANEL CUT-OUD-SUB COMBINATION FEMALE 5W5S SOLDER CO	UT
	NY WAY, AN A THIRD PA ION.						appd.	21.09.2015	Fisch	ner		CUP
	ANY V ANY V O A TH SION.	CAD					norm				with open 4-40 UNC thread	
	SATES	TER					d-old				dwg no:	
	DRAWING DDUCED I SSED ON TEN PERM	ALT	AL				_	45 =			15K1A1664	A3
	DRA ODU ASSE TEN ERSF	NOT	а	Original				N E		13K1A1004	: 2	
	THIS DRAWING REPRODUCED BE PASSED ON WRITTEN PERN OWNERSHIP A	D0 I	rev.	description	date	name	7		<b>7 8 8 9</b>		part no: SEE SHEET 1	·

## **Mouser Electronics**

**Authorized Distributor** 

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

CONEC: 15-006823