

Product Advisory

Issue Date: January 20, 2023

Change Type:

OCP3.0 pull tab bracket update

Parts Affected:

BRCM Part Number	New Revision Number
BCM957504-N425G	30

Description and Extent of Change:

The LED port markings "L" for Link and "A" for Activity are added for each port on the bracket.

Reasons for Change:

Consistency with other brackets

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The adapter specification will remain the same. No changes to adapter form, fit, function, quality and reliability.

Effective Date of Change:

This will be implemented as running change starting after March 30, 2023.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.