

Product Advisory



Issue Date: Feb 8, 2023

Change Type:

Supply continuity. BOM component change only.

Description and Extent of Change:

The heatsinks used on the adapters listed in the table below are being updated to remove the heatsink detection logic pins, also known as TOGO pins. The pins supported a now deprecated feature used to detect if the heatsink is missing. The picture on the left is the existing heatsink with TOGO pins and the picture on the right is new heatsink without the TOGO pins.



Reasons for Change:

The heatsink detection feature has been deprecated

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The adapter specification will remain the same. No changes to adapter form, fit, function, quality and reliability.

Effective Date of Change:

The update is being implemented as a running change. Product shipments start after March 30, 2023.

Parts Affected:

BRCM Part Number	New Revision Number	BRCM Part Number	New Revision Number
BCM957314A3143CC	27	BCM957414A4141DLPC	21
BCM957412A4120AC	19	BCM957414A4142CC	22
BCM957412A4120DC	19	BCM957414A4142HC	9
BCM957412A4120DLPC	20	BCM957414M4142C	17
BCM957412A4121HC	13	BCM957414M4142DC	13
BCM957412M4122C	16	BCM957414M4143C	13
BCM957414A4140C	14	BCM957416A4160C	13
BCM957414A4141DD	3	BCM957416A4160DC	14
BCM957414A4141DDLPC	3	BCM957416A4160DLPC	15
BCM957414A4141DDLT	5	BCM957416A4162HC	9
BCM957414A4141DDT	5		



Lenovo Part Number	New Revision Number	Lenovo Part Number
BCM957414A4141LC2	4	SN37A91440
BCM957414A4141LCF2	3	03GX198
BCM957416A4160LC	21	SN30L27797
BCM957416A4160LFRU	18	00YK535

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.