

Product Advisory

Issue Date: September 21, 2020

Change Type:

New revision of Datasheet

Parts Affected:

BCM89230B1BCFBG
BCM89230B2BCFBG
BCM89230B1BCFBGT
BCM89230B2BCFBGT
BCM89231B1BPBG
BCM89231B2BPBG
BCM89231B1BPBGT
BCM89231B2BPBGT

Description and Extent of Change:

- 8923X-DS109
 - Added B2 parts to Table 64, Ordering Information

Reasons for Change:

Additional versions of product added to the datasheet

Effect of Change on Fit, Form, Function, Quality, or Reliability:

Errata fixed in B2 version of the device. See Errata document 8953X-8923X-ES105 for details. If not affected by the errata you can stay with the B1 version of the product (no changes to B1 production support).

Effective Date of Change:

Datasheet 823X-DS109 was released on August 28, 2019

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.