Quick start guide UP² (Squared) Chassis



Parts List

- One top cover with UP square logo.
- One base case.
- Four (4) M2.5-25.8 Hex Stand-off.
- Four (4) 2.5-5 Sheet Metal machine screws.
- Two (2) 2.3-10 Sheet Metal Tapping screws.
- Two (2) Vesa screws.


Not included with the kit, you may need to prepare:

- UP square board.
- Small screwdriver.


Assembly steps

- 1. Start with screw the 4 Hex Stand-off on the board.
- 2. Place the board into the base case, check well with the 4 sides exactly that match the IO sides.
- 3. Take machine screws, and holding the bottom base with board in place, feed the screws from the bottom, through the screw holes, wiggling them a little bit to get them to line up.
- 4. Click the top cover with base bottom with board.
- 5. Final step is screw the remaining Metal tapping screws.
- 6. Make sure they are finger tight, so they won't come undone during use.

EP-CHUPSABSVESA



Exploded view on the chassis, including Hex stand-offs



Screw locations (VESA Screws in Red, bottom left) from the bottom view

As always, go check out up-community.org for support and more information about your UP board

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

AAEON:

EP-CHUPSABSVESA