

FORM HC0011-5-8 1

	PART NUMBER	CL NUMBER	NUMBER OF	DIMENSION OF CONNECTOR, PCB MOUNTING PATTERN AND STENCIL				DIMENSION OF DRAWING FOR PACKING						DIMENSION OF RECOMMENDED FPC			
			CONTACT	А	В	С	D	h	E	F	G	Н	J	К	L	М	N
\triangle	FH29DJ-44S-0.2SHW(99)	-	44	10.62	8.4	9.24	9.615	22	11.62	11.5	-	24	25.4	29.4	10.06	9.2	8.87
\triangle	FH29DJ-50S-0.2SHW(99)	CL580-0338-6-99	50	11.82	9.6	10.44	10.815	25	12.82	11.5	-	24	25.4	29.4	11.26	10.4	10.07
	FH29DJ-60S-0.2SHW(99)	CL580-0343-6-99	60	13.82	11.6	12. 44	12.815	30	14.82	11.5	1	24	25.4	29.4	13.26	12.4	12.07
	FH29DJ-70S-0.2SHW(99)	CL580-0336-0-99	70	15, 82	13.6	14.44	14.815	35	16.82	11.5	-	24	25.4	29. 4	15. 26	14.4	14.07
	FH29DJ-80S-0.2SHW(99)	CL580-0341-0-99	80	17.82	15.6	16.44	16.815	40	18.82	14.2	28.4	32	33. 4	37.4	17.26	16.4	16.07
	FH29DJ-90S-0.2SHW(99)	CL580-0340-8-99	90	19.82	17.6	18. 44	18.815	45	20.82	20.2	40.4	44	45.4	49. 4	19. 26	18.4	18.07
	FH29DJ-100S-0,2SHW(99)	CL580-0335-8-99	100	21.82	19.6	20.44	20.815	50	22.82	20.2	40.4	44	45.4	49. 4	21.26	20.4	20.07
	FH29DJ-110S-0,2SHW(99)	- 0R1	110	23.82	21.6	22. 44	22.815	55	24.72	20.2	40.4	44	45.4	49. 4	23.26	22. 4	22.07
	FH29DJ-120S-0,2SHW(99)	CL580-0342-3-99	120	25.82	23.6	24. 44	24.815	60	26.82	20.2	40.4	44	45.4	49.4	25. 26	24.4	24.07
	A % CONTACT	POSITIONS WITH	HOUT	CODE		IBERS	ARE	CUF	RENT	LY U	NDER	PLA	NNIN	G.			

PLEASE CONTACT HIROSE FOR DETAILED INFORMATION ABOUT PRODUCT VARIATION.

HRS DRAWING NO.
PART NO.
CODE NO.

EDC-355229-99-00 FH29DJ-*S-0.2SHW(99)

CL580

С

This connector is small and thin and requires delicate and careful handling. Read through the instructions shown below and handle the connector properly. Each values indicating here are for reference and may differ from standard value.

[INSTRUCTIONS FOR MOUNTING ON THE BOARD]

♦Warp of Board

Minimize warp of the board as much as possible. Lead co-planarity including reinforced metal fittings is 0.1 mm or less. Too much warp of the board may result in a soldering failure.


♦Flexible board design


Please make sure to put a stiffener on the backside of the flexible board. We recommend a glass epoxy material with the thickness of 0.3mm MIN.

♦Load to Connector

Do not add 0.5N or greater external force when unreel or pick and place the connector etc.

FORM HC0011-5-8 1






INSTRUCTIONS ON INSERTING FPC AND CONNECTION

♦ Use of the Actuator

1. Be very careful not to apply excessive force when releasing the actuator in the initial position (with no FPC inserted).

If you use your nail or finger as shown below the terminals may be deformed.




Defomation of the terminal upper arm


Example 1


Example 2

2. The actuator rotates around the rotational axis as shown below. Please rotate the actuator.




3. Please do not push downwards to the actuator with more than 0.5N force, as shown below. Otherwise, the actuator may fall off or be damaged. $_$





4. The actuator will not open more than 135°. Do not apply any force backward beyond this point. Otherwise, the actuator may come off or break.




}		DRAWING NO.	EDC-355229-99-00	
	H 75	PART NO.	FH29DJ-*S-0.2SHW(9	9)
		CODE NO.	CL580 Z	$\frac{5}{6}$
			ā	

5. Move the actuator at approximately the center-

(It may break if operate the edge of the actuator with FPC inserted.)

6. Do not pinch or pick the actuator to lift it as shown below. Otherwise, it may break.

(Do not carry out any operation other than rotating the actuator as shown in 2 above.)



♦Direction of Contacts


This connector has contacts on the bottom. Thus, insert the FPC with the exposed conductors face down.


♦Inserting the FPC

1. Insert the FPC by about 10 degrees along the surface and at a right angle to the connector. Insert it properly to the very end.

If the FPC is inserted at a slant (incorrectly).

the conductors may short-circuit due to pitch shift or the edge of the FPC may catch in the terminals resulting in deformation of the terminals.





2. Do not insert the FPC diagonally from above.


If the FPC is inserted at a slant (incorrectly) as shown below in the FPC insertion process, the FPC may bend and patterns may break or the FPC may not insert completely, resulting in improper conduction.

*Keep a sufficient FPC insertion space in the stage of the layout in order to avoid incorrect FPC insertion.

Besides, it is not difficult to insert FPC correctly all the way to the end.

Design the proper layout of parts.

*Make adjustments with the FPC manufacturer for FPC bending perfomance and wire breakage.



♦Checking the Locking Condition

FORM HC0011-5-8 1

In the locked condition, make sure that the actuator is horizontal on the board surface. Do not apply excessive force to it near the 0° position of the actuator. Otherwise, the terminals may be deformed. (Allowable force: 1 N or less)

INSTRUCTIONS ON FPC LAYOUT AFTER CONNECTION


♦Load to FPC

Be very careful not to apply any force to the FPC after inserting it.

Otherwise, the connector may become unlocked or the FPC may break.

Fix the FPC, in particular, when loads are applied to it continuously.

Design the FPC layout with care not to bend it sharply near the insertion opening.




INSTRUCTIONS ON REMOVING FPC

◆Release the actuator at approximately the center.

(It may break if operate the edge of the actuator with FPC inserted)

♦Release the actuator to remove the FPC.

Remove the FPC by about 10 degrees along the surface.




IOTHER INSTRUCTIONS

♦Instructions on Manual Soldering

Follow the instructions shown below when soldering the connector manually during repair work, etc.

- 1. Do not perform reflow soldering or manual soldering with the FPC inserted into the connector.
- 2. Do not heat the connector excessively. Be very careful not to let the soldering iron contact any parts other than connector leads. Otherwise, the connector may be deformed or melt.
- 3. Do not use excessive solder (or flux).
- If excessive solder (or flux) is used on the terminals, solder or flux may adhere to the contacts or rotating parts of the actuator, resulting in poor contact or a rotation failure of the actuator.



В

2 3 4 5