BROADCOM

PA- 294946

Product Advisory

Issue Date: June 5, 2025

Change Type:

PCB Component Footprint change

Parts Affected:

Description	Current Revision	Updated Revision
9560-16i SINGLE KIT, 8GB, GA, 00	05-50077-00	14
9560-16i 8GB, GA, 00	03-50077-00	13
9560-16i SINGLE KIT, 8GB, GA, 00	05-50077-01	14
9560-16i 8GB, GA, 00	03-50077-01	13


Description of Change:

The 9560-16i/8i PCB was modified to increase the pad width for the power manager component.

This part is dual sourced and there are slight differences in each vendor's footprint. One vendor's part is more susceptible to being placed off the PCB pads causing resulting in potential manufacturing yield loss. To prevent this, the width of the pads was increased to accommodate both parts. The following picture shows minor changes in the pad width as shown in yellow. There were no other changes to the board.



Original Pads



Updated Pads

Effect of Change:

There is no change to form, fit, or functionality.

Effective Date of Change:

Adapters with this update will begin to ship after August 1, 2025. The cut-in will be noted by the revision in the table.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.