## PRODUCT CHANGE NOTIFICATION

Date: September 10, 2015
PCN: PCN LEDIL 107

**Subject:** **PCN 106.a - Discontinuation of duplicate assemblies**

Description: As part of our continuous improvement process regarding the logistics and quality of our products LEDiL is discontinuing LISA2 products with duplicate product structure. Discontinued products share the same components and structure with products that are replacing them so there are no changes on optical performance or specifications of the affected products.

Time line: This change is valid immediately

Changes:

| DISCONTINUED PRODUCT | **REPLACED BY** |
|---|---|
| FP11000_LISA2-WW-PIN | **FP10994_LISA2-WW-PIN** |
| FP11057_LISA2-RS-PIN | **FP11056_LISA2-RS-PIN** |
| FP11079_LISA2-W-CLIP | **FP11073_LISA2-W-CLIP** |
| FP11080_LISA2-WW-CLIP | **FP11074_LISA2-WW-CLIP** |
| FP11855_LISA2-O-90-PIN | **FP11853_LISA2-O-90-PIN** |
| FP10998_LISA2-M-PIN | **FP10992_LISA2-M-PIN** |
| FP11123_LISA2-O-CLIP | **FP11122_LISA2-O-CLIP** |
| FP11087_LISA2-RS-CLIP | **FP11086_LISA2-RS-CLIP** |
| FP10999_LISA2-W-PIN | **FP10993_LISA2-W-PIN** |
| FP11078_LISA2-M-CLIP | **FP11072_LISA2-M-CLIP** |
| FP11954_LISA2-WWW-PIN | **FP11951_LISA2-WWW-PIN** |
| FP11860_LISA2-O-90-CLIP | **FP11858_LISA2-O-90-CLIP** |
| FP11127_LISA2-O-PIN | **FP11126_LISA2-O-PIN** |
| FP11955_LISA2-WWW-CLIP | **FP11952_LISA2-WWW-CLIP** |

Contact information: Tero Mäkinen
LEDIL Oy
Salorankatu 10
24240 SALO, FINLAND
tero.makinen@ledil.com