MICROCHIP

Product Change Notification - SYST-09AMJS720

Date:

13 Aug 2019

Product Category:

Development Tools; Ethernet Switches

Affected CPNs:

📄📊

Notification subject:

ERRATA - KSZ8873 Errata Document Revision

Notification text:

SYST-09AMJS720

Microchip has released a new Product Documents for the KSZ8873 Errata of devices. If you are using one of these devices please read the document located at KSZ8873 Errata.

Notification Status: Final

Description of Change: 1) Converted to Microchip format. 2) Module 2: These bits control Force 100," changed to "These bits control Force 100BASE-TX. 3) Module 7: Added new erratum: SMI management interface does not function if SPISN pin is not pulled high 4) Module 8: Added new erratum: Receiver error in 100BASE-TX mode following Soft Power Down.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 13 August 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

KSZ8873 Errata

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our PCN home page select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the PCN FAQ section.

If you wish to change your PCN profile, including opt out, please go to the PCN home page select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

KSZ8873FLL
KSZ8873FLL-EVAL
KSZ8873FLLI
KSZ8873MLL
KSZ8873MLL-AM
KSZ8873MLL-AM-TR
KSZ8873MLL-EVAL
KSZ8873MLLI
KSZ8873MLLJ
KSZ8873MML
KSZ8873MMLI
KSZ8873RLL
KSZ8873RLLI
KSZ8873RLLI-TR
KSZ8873RLLU