ABRACON

Engineering/Process Change Notice

ECN/PCN No.: M1774

For Manufacturer

Product Description:	**Abracon Part Number / Part Series:**	☐ Documentation only ☒ ECN ☐ EOL	☒ Series ☐ Part Number(s)
Abracon Varistors	AMCV-SH0806, AMCV-SS0806, AMCV-SS1210, AMCV-SS1812 AMCV-SS2220		
Affected Revision: Initial revision	**New Revision:** A	**Application:**	☐ Safety ☒ Non-Safety

Prior to Change:
The following series has the incorrect MSL rating of 2.
AMCV-SH0806
AMCV-SS0806
AMCV-SS1210
AMCV-SS1812
AMCV-SS2220

After Change:
The following series have been corrected to MSL rating of 1.
AMCV-SH0806
AMCV-SS0806
AMCV-SS1210
AMCV-SS1812
AMCV-SS2220

Cause/Reason for Change:
Incorrect MSL rating on several initial revision varistor datasheets.

Change Plan

Effective Date: 11/19/2026	**Additional Remarks:**

Change Declaration:
Changes described here do not change the product form, fit or function.

Issued Date: 11/19/2026	**Issued By:** *Gerald Capwell*	**Issued Department:** Engineering
Approval: *Gerald Capwell* Director, Engineering	**Approval:** *Reuben Quintanilla* Quality Director	**Approval:** *Ying Huang* Purchasing Director

For Abracon EOL only

Last Time Buy (if applicable):	**Alternate Part Number / Part Series:**

Additional Approval:	**Additional Approval:**	**Additional Approval:**

Customer Approval (If Applicable)

Qualification Status:

☑ Approved ☐ Not accepted

Note: It is considered approved if there is no feedback from the customer 1 month after ECN/PCN is released.

Customer Part Number:	**Customer Project:**

Company Name:	**Company Representative:**	**Representative Signature:**

Customer Remarks: