BOURNS®

Product Obsolescence Memo

INDUCTIVE COMPONENTS



February, 2014

Bourns® Model RL110S Series
Radial Lead RF Chokes to be Discontinued

Bourns will be discontinuing the Model RL110S Series Radial Lead RF Choke. A lack of sales volume and diminishing demand necessitates this action. Regrettably, replacement products are not available at this time.

Obsolete Part Numbers:

RL110S-100M-RC	RL110S-560L-RC	RL110S-331L-RC
RL110S-120M-RC	RL110S-680L-RC	RL110S-391L-RC
RL110S-150M-RC	RL110S-820L-RC	RL110S-471L-RC
RL110S-180M-RC	RL110S-101L-RC	RL110S-561L-RC
RL110S-220M-RC	RL110S-121L-RC	RL110S-681L-RC
RL110S-270M-RC	RL110S-151L-RC	RL110S-821L-RC
RL110S-330L-RC	RL110S-181L-RC	RL110S-102L-RC
RL110S-390L-RC	RL110S-221L-RC	
RL110S-470L-RC	RL110S-271L-RC	

Please plan for the following deadlines:

Last time buy date: July 31, 2014
Last time ship date: February 28, 2015

Should you have any questions or need additional information, please feel free to contact Customer Service/Inside Sales.