EOL-253341

Product Obsolescence Notification

Issue Date: 27-September-2022

Dear Customer:

Broadcom regrets to announce the obsolescence of the following products:

Broadcom Part Numbers	Description	LTB Date (LTB)	LTS Date (LTS)	Minimum Order (MOQ)	Suggested Replacement
BCM6302KMLGT	ADSL Line Driver	10/11/2022	3/31/2023	25,000u up to the FG that Broadcom has on hand	BCM6303 Line Driver
BCM6302KMLG	ADSL Line Driver	10/11/2022	3/31/2023	2,270u up to the FG that Broadcom has on hand	BCM6303 Line Driver
BCM63137USA01	63137U+6302+4360x2	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver
BCM63167UTT00	63167U+6302	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver
BCM63168DVSY00	63168V + 6302 + 4360	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver
BCM63168ESG01	63168E+6302+53124S	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver
BCM63168SQ02	63168U+6302+43602	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver
BCM63168USA01	63168U+6302	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver
BCM63168USAP01	63168U+6302(T/R)+AC201	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver
BCM63168USAS01	63168U+6302+AC201	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver
BCM63168USH03	63168U+6302	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver
BCM63168USR01	63168U+6302	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver
BCM63168VSJ01	63168V+6302	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver

BCM63168VSL00	63168V+6302+4360	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver
BCM63168VSU01	63168V+6302	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver
BCM63268ESD01	63268E+6302+54610x2	10/11/2022	3/31/2023	None, up to the FG that Broadcom has on hand	BCM63146 or BCM63178 xDSL SOC with BCM6303 Line Driver

Please provide your Broadcom Sales Office with your lifetime Last Time Buy order requirements (LTB) for the above products no later than the date noted in the above table. These orders are non-cancelable, non-returnable and cannot be rescheduled. Orders received after the Last Time Buy (LTB) order date noted in the above table cannot be accepted.

The last requested delivery date for these orders may not be later than the Last Time Ship (LTS) date noted in the above table. Due to inherent variations in yields, Broadcom reserves the right to ship up to 5% under the original last time buy quantity, and this quantity will fully satisfy Broadcom's obligation to deliver that product under this last time buy agreement.

All last time buy orders must be placed based on Broadcom's minimum order quantity (MOQ) requirements per the above table. All prior commitments regarding Broadcom's minimum order requirements do not apply to last time buy orders. Broadcom reserves the right to limit last time buy quantities based on capacity and material availability.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.