

Product Change Notification

PCN #: 6A-2022

DATE: 7th June 2022

1 PRODUCTS AFFECTED – TOP LEVEL PART NUMBERS

Laird Part Number	Old Rev	New Rev	Description
ST60-2230C-P	2.2	2.2	Module, Sterling 60 Series PCIE/UART M.2 Module
ST60-2230C-PU	2.2	2.2	Module, Sterling 60 Series PCIE/USB M.2 Module
SU60-2230C-P	2.2	2.2	Module, Summit 60 Series PCIE/UART M.2 Module
SU60-2230C-PU	2.2	2.2	Module, Summit 60 Series PCIE/USB M.2 Module

2 DESCRIPTION OF CHANGES

Rev	Rev	Description
2.2	2.2	Add TI's TPS72718DSE as alternative part in U4 with C52 changed to 0ohm resistor

3 REASON FOR CHANGE

- Add alternative parts to reduce serious materials shortage problem due to global supply chain challenges.

4 ANTICIPATED IMPACT OF THE CHANGE

- None. There is no impact on form, fit, or function.

5 METHOD OF IDENTIFYING THE CHANGED PRODUCT

5.1 Module Labels (on device)

- No change on product label but it can be easily identified the hardware difference.

Existing Production BOM:

U4=TPS71718DSE; C51=0.01uF/10V

Device marking on TPS71718DSE is "G6"

The information in this document is subject to change without notice.



Alternative Production BOM:

U4=TPS72718DSE; C51= 0 ohm (0201)
Device marking on TPS72718DSE is "GT"



The information in this document is subject to change without notice.

6 FACTORY EFFECTIVITY DATE

Immediate Implementation after date code: 1122221 (SSYYWWD)

SS = Supplier code

YY = last two numbers of the year (ex: 18=2018, 19=2019)

WW = Week of the year

D = day of the week (ex: Sun=1, Mon=2, Tue=3, Wed=4, Thu=5, Fri=6, Sat=7)

7 CONTACT INFORMATION:

Headquarters

Laird Connectivity
50 S Main St., Suite 1100
Akron, OH 44308 USA
Tel: 1(330) 434-7929
Fax: 1(330) 434-7931

PCN Contact

pcn@lairdconnect.com

Website

www.lairdconnect.com

Technical Support

support@lairdconnect.com

Sales Contact

sales@lairdconnect.com

Product Change Notices (PCNs) will be distributed at the discretion of Laird Connectivity. Occasionally, Laird Connectivity may adjust product revision levels for internal tracking purposes only, and customers may not receive formal notifications associated with those revision changes.