MACOM™
Partners from RF to Light

PCN Number: PCN-01237		**PCN Date:** April 22, 2019
Title: Change to MAAP-011233 Lid Attach Epoxy		
Date of change: May 2019 **Proposed last Ship Date:**		**Estimated Sample Availability/ Qualification Completion:** On request See QTR-0467
Change Classification:	**Major** ☐	**Minor** ■
Change Type:		
Assembly Site ☐	Design ☐	Electrical Specification ☐
Test Site ☐	Assembly Process ☐	Mechanical Specification ☐
Wafer Process ☐	Assembly Materials ■	Packing/Shipping/Labeling ☐

PCN Details

Description of Change:

A minor change is being made to the lid attach epoxy. The epoxy is being changed from Epo-Tek B9021-15 to Epo-Tek 131-8-1.

Reason for Change:

The lid attach epoxy is being changed to increase the lid shear strength of the device.

Products Affected:

MAAP-011233
MAAP-011233-TR0500
MAAP-011233-TR1000

Anticipated impact on Fit, Form, Function:

No changes to fit, form, or function. Enhanced product reliability is expected.

Changes to product identification resulting from this PCN:

None

Material Declaration updated due to this change: Yes ■ No ☐