CUSTOMER SERVICE
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000747

DATE: 27-Jul-12

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1991L-F5+	DS1977-F5#	25-Jan-2013	27-Jul-2014	No longer manufacturable
Discontinuance	DS2409P+	NONE	25-Jan-2013	27-Jul-2014	No longer manufacturable
Discontinuance	DS2409P+T&R	NONE	25-Jan-2013	27-Jul-2014	No longer manufacturable
Discontinuance	DS2450S+	NONE	25-Jan-2013	27-Jul-2014	No longer manufacturable
Discontinuance	DS2450S+T&R	NONE	25-Jan-2013	27-Jul-2014	No longer manufacturable
Discontinuance	MAX98000ETE+	NONE	25-Jan-2013	27-Jul-2014	Part was never released
Discontinuance	MAX9880EWM+	MAX9880AEWM+	25-Jan-2013	27-Jul-2014	Part has direct replacement
Discontinuance	MAX9880EWM+T	MAX9880AEWM+T	25-Jan-2013	27-Jul-2014	Part has direct replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: AUGUST 27, 2012