MICROCHIP

Product Change Notification: SYST-09DBYI510

Date:

19-Sep-2025

Product Category:

System On Chip Fpgas

Notification Subject:

PolarFire® SoC FPGA Production Devices Errata

Affected CPNs:

SYST-09DBYI510_Affected_CPN_09192025.pdf
SYST-09DBYI510_Affected_CPN_09192025.csv

Notification Text:

SYST-09DBYI510
Microchip has released a new Document for the PolarFire® SoC FPGA Production Devices Errata of devices. If you are using one of these devices please read the document located at **PolarFire® SoC FPGA Production Devices Errata**. **Notification Status:** Final **Description of Change:** • SD compliance tests are completed. • Added row to Table 1-1. Summary of PolarFire® SoC FPGA Errata for "External VERIFY_DIGEST with POR Digest Check for Fabric Components." • Deprecated Feature: Use of External VERIFY_DIGEST with POR Digest Check for Fabric Components.   **Impacts to Data Sheet:** None **Reason for Change:** To improve productivity. **Change Implementation Status:** Complete

Date Document Changes Effective: 19 Sep 2025

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

PolarFire® SoC FPGA Production Devices Errata

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from