MICROCHIP

Product Change Notification - SYST-17PEVC599

Date:
18 Oct 2019
Product Category:
Computing Embedded Controllers
Affected CPNs:

Notification subject:
ERRATA - SCH322x Silicon Errata and Data Sheet Clarification
Notification text:
SYST-17PEVC599
Microchip has released a new Product Documents for the SCH322x Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at SCH322x Silicon Errata and Data Sheet Clarification.

Notification Status: Final

Description of Change: In Data Sheet Clarifications, Module #4 - 8042 Keyboard Controller - “Runtime Register 0x5” changed to “Runtime Register 0x5C”.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 18 Oct 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A
Attachment(s):

SCH322x Silicon Errata and Data Sheet Clarification

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our PCN home page select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the PCN FAQ section.
If you wish to change your PCN profile, including opt out, please go to the PCN home page select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

SCH3222-SX
SCH3222-SX-TR
SCH3222I-SX
SCH3222I-SX-TR
SCH3224-SY
SCH3224-SY-TR
SCH3224I-SY
SCH3224I-SY-TR
SCH3226-SY
SCH3226-SY-TR
SCH3226I-SY
SCH3226I-SY-TR
SCH3227-SZ
SCH3227-SZ-TR
SCH3227I-SZ
SCH3227I-SZ-TR