PCN#20140311001
TPS2411PW Top-side symbol font change
Information Only

 Date: 3/14/2014
 To: MOUSER PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this PCN are for your information only. Please see the attachment details for the planned implementation date.

This notification period is per TI's standard process. Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services
Phone: +1(214) 480-6037
Fax: +1(214) 480-6659

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
TPS2411PW	null

Technical details of this Product Change follow on the next page(s).

PCN Number:	20140311001			PCN Date:	03/14/2014
Title:	TPS2411PW Top-side symbol font change				
Customer Contact:	PCN Manager	Phone:	+1(214) 480-6037	Dept:	Quality Services
Proposed 1st Ship Date:	03/14/2014		Estimated Sample Availability:		03/14/2014

Change Type:

☐	Assembly Site	☐	Assembly Process	☐	Assembly Materials
☐	Design	☐	Electrical Specification	☐	Mechanical Specification
☐	Test Site	☒	Packing/Shipping/Labeling	☐	Test Process
☐	Wafer Bump Site	☐	Wafer Bump Material	☐	Wafer Bump Process
☐	Wafer Fab Site	☐	Wafer Fab Materials	☐	Wafer Fab Process
		☐	Part number change		

PCN Details

Description of Change:

The family of TPS2411PW devices will be marked with a slightly different font as shown below.

	From	To
Device Symbol		

Reason for Change:

To create room for additional character for graded device.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

None

Changes to product identification resulting from this PCN:

Top mark with new font.

Product Affected:

TPS2411PW	TPS2411PWG4	TPS2411PWR	TPS2411PWRG4

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com