Product Discontinuance

Document #:PD24446X4
Issue Date: 04 Mar 2022

Title of Change:	Reactivation of previously discontinued part (FDS9958 & NDS9407).
Last Time Buy Date:	N/A
Last Ship Date:	N/A
Contact information:	Contact your local onsemi Sales Office or Ruben.Lopez@onsemi.com
Type of notification:	Customers must notify onsemi (<PCN.Support@onsemi.com >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

Description and Purpose:

onsemi wishes to inform customers of the reactivation of devices below that was previously discontinued in **PD24446X**.

The parts shall be considered active.

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:
Tom Siegel (tom.siegel@onsemi.com)
☎ +1 765 868 5022
USA

Europe:
Andrej Tomasik (andrej.tomasik@onsemi.com)
☎ +421 33790 2229
Slovakia

Japan:
Isao Usuki (isao.usuki@onsemi.com)
☎ +81 3 6880 1771
Japan

Asia Pacific:
Stephen Ng (stephen.ng@onsemi.com)
☎+852 2689 0209
China

List of Affected Parts:

Note: *Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the* ***PCN Customized Portal****.*

Device to be Discontinued	Replacement part	Supplier
NDS9407	N/A	N/A
FDS9958	N/A	N/A