Product Change Notification: SYST-18DLZI542

Date:

11-Mar-2026

Product Category:

32-Bit Microcontrollers

Notification Subject:

PIC32CM LE00/LS00/LS60 Family Silicon Errata and Data Sheet Clarifications

Affected CPNs:

SYST-18DLZI542_Affected_CPN_03112026.pdf
SYST-18DLZI542_Affected_CPN_03112026.csv

Notification Text:

SYST-18DLZI542
Microchip has released a new Document for the PIC32CM LE00/LS00/LS60 Family Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at **PIC32CM LE00/LS00/LS60 Family Silicon Errata and Data Sheet Clarifications**. **Notification Status:** Final **Description of Change:** Added the following new errata: • SERCOM I2C: 2.12.2 I2C Host Mode **Impacts to Data Sheet:** None **Reason for Change:** To improve productivity. **Change Implementation Status:** Complete **Date Document Changes Effective:** 11 Mar 2026

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

PIC32CM LE00/LS00/LS60 Family Silicon Errata and Data Sheet Clarifications

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from