SYMBOL DEFINITION		MISSING SYMBOLS
X DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL CODE DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO. OF INSPECTIONS REQUIRED: NA LOT NO. SIZE: NO	NO MISSING SYMBOL NUMBER

| REVISION HISTORY | | |