

300A AC Clamp-on Adaptor

Allows multimeters to measure up to 300A AC

With 10mV/A output

Features:

- Banana plugs connect to COM and V sockets of any multimeters for clamp-on current measurements
- 1.2" (30mm) clamp jaw opening (500MCM)
- Measures AC Current and converts it to an AC mV output for displaying Current on any multimeter
- Banana plugs connect into standard multimeter sockets
- 2.5% basic accuracy
- Dimensions: 9.5x3.6x1.7" (24.1x 9.1x4.3mm); Weight: 10oz (265g)
- Complete with built-in 10' (3m) cable with banana plugs
- No battery required



10mV/A output for use on multimeters with 1mV ACV resolution and with graphical multimeters



Ordering Information:

CA310AC Clamp-On Adaptor (10mV/Amp output)



