



LEMO USA, Inc.
 635 Park Court
 P.O. Box 2408
 Rohnert Park, CA 94927-2408


Main (707) 578-8811
 Toll Free (800) 444-5366
 Fax (707) 578-0869

PRODUCT UPDATE


Number: #067
 By: LEMO HQ / Dennis Warren
 Date: June 23, 2010

New Improved Mid-pieces for In-line 0B Receptacles

Size 0B receptacles now have an improved mid-piece and associated shells. The new mid-pieces will make the 0B in-line receptacles easier to assemble. The 2 mid-piece halves will capture the insert within the mid-pieces rather than that of the current design where the insert is at the end of the mid-pieces.



The following models will be affected, PH*.0B, PK*.0B and PF*.0B. (* = various option keyways)





Before



After

OLD Mid-piece Part Numbers: (PHG.0B.150.LN + PHG.0B.151.LN = **PHG.0B.155.LNN**)

NEW Mid-piece Part Numbers: (FGG.0B.151.LNP + FGG.0B.150.LNP = **FGG.0B.155.LNNP**)

The new mid-pieces will only work with the new style shell. The internal construction for the new mid-piece is different.

The completed in-line receptacle is form, fit or function compatible with current and older mating plugs.

If you have any questions or concerns regarding this change, please contact our customer service department or applications department at: 1-800-444-5366.

Thank you for your continued support of LEMO products.