

PRODUCT CHANGE NOTIFICATION (PCN)

Release Date: 05/29/2026 00:00:00

Product Category: **COM Express Type 6 / Starterkits**

Models Affected: **Express-ADP/RLP**

Purpose of Notification: BOM Update

In accordance with the Lifecycle SolutionsSM program, ADLINK Technology announces a change for the Express-ADP/RLP series of products. This document describes changes to BOM used in these products.

Description of Change:

Type	Description
Summary	This product change notification describes a BOM update.
Causes	A leakage issue was identified on the unused 5VSB power rail in AT mode, which may cause the EC to incorrectly detect the 5VSB status, potentially posing a risk to the EC.
Solutions	Update the BOM to resolve the identified issues.

Revision Information

Old Revision	New Revision	Model No
91-77107-104E	91-77107-105E	I-Express-ADP-i5-12600HE-Kit
91-77107-605E	91-77107-606E	I-Express-RLP-i3-13300HRE-Kit
91-72139-S010	91-72139-S020	t1Express-RLP-i3-13300HRE
91-72139-T010	91-72139-T020	t1Express-RLP-i7-1365URE
91-72139-1S0D	91-72139-1S1D	t1Express-RLP-i7-1365URE+ET+CC
91-72139-Q020	91-72139-Q030	t1Express-RLP-i7-13800HRE
91-72139-0S2D	91-72139-0S3D	t1Express-RLP-i7-13800HRE+ETT+CC
91-72139-J020	91-72139-J030	t1Express-RLP-i7-13800HRE-VGA
US-72139-2C1S	US-72139-2C2S	t1Express-RLP-i7-13800HRE/M64G/ETT
UPC-736905C-0000	UPC-736905C-0000	t1Express-RLP-i7-13800HRE/M64G/ETT/CC
US-72139-0T0E	US-72139-0T1E	t1Express-RLP-i7-13800HRE/M96G Sealevel
US-72139-3C0S	US-72139-3C1S	t1Express-RLP-i7-13800HRE/M96G/ETT

PRODUCT CHANGE NOTIFICATION (PCN)

91-72139-2030	91-72139-2040	Express-ADP-i3-12300HE
91-72139-7030	91-72139-7040	Express-ADP-i5-1245UE
91-72139-4030	91-72139-4040	Express-ADP-i5-1250PE
US-72139-0C10	US-72139-0C10	Express-ADP-i5-1250PE Brain
91-72139-1030	91-72139-1040	Express-ADP-i5-12600HE
US-72139-1C10	US-72139-1C20	Express-ADP-i5-12600HE Brain
91-72139-0030	91-72139-0040	Express-ADP-i7-12800HE
91-72139-V030	91-72139-V040	Express-RLP-U300E
91-72139-U030	91-72139-U040	Express-RLP-i3-1315UE
US-72139-0S0D	US-72139-0S1D	Express-RLP-i7-1365URE/M32G/ETT/CC
91-72139-N020	91-72139-N030	Express-RLP-i7-1370PE
91-72139-K030	91-72139-K040	Express-RLP-i7-13800HE

Implementation Date:

Running Change Immediately

Sample Availability:

Please contact your ADLINK sales representative.

An important part of the Lifecycle Solutions program for ADLINK products is to provide customers with notice of any changes that might affect long-term product usage or availability. Except for circumstances requiring immediate changes, ADLINK normally provides a few months advance notice of changes that affect the form, fit, or function of the product. If you have any questions or concerns about this notice, please contact your ADLINK sales representative.

If you have technical questions about this product notification, please contact your ADLINK Field Applications Engineer directly. Otherwise, you can call ADLINK at 1-800-966-5200 or 408-360-0200. For online technical support, please visit our Ask an Expert page at <https://www.adlinktech.com/en/Askexpert>.