



Product Name:	HPL538 - 538 - FFC / FPC SYSTEMS	
	58LF Flex -2.54mm pitch Duflex Housings	
Product Manager:	Shoichi.Omote	
Subject:	Notification of Change with Immediate Effectivity	
Distribution:	Affected customers	
Type of Change:	Materials Change	
Change Description:	<p>Use of alternative color of POCAN plastic material (white instead of blue) within our Duflex part</p> <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;"> <p>Original color (Blue)</p>  </div> <div style="text-align: center;"> <p>Alternative color (natural)</p>  </div> </div>	
Reason for Change:	<p>Due to an unexpected and unforeseen non-availability of Pocan B4235 blue thermoplastics, Amphenol will not be able to deliver parts in blue colour as per immediate effect. As from the date of this PCN, in order to ensure the supply of the affected Duflex part numbers, Amphenol will deliver these part numbers in the same material (Pocan B4235) with the exact same technical characteristics but in a natural colour for a period of time still to be defined. Until the availability of blue Pocan material is fully recovered & secured and unless clearly specified by customers, Amphenol reserves the right to deliver the affected part series either in blue or natural color according to material availability. More detail is explained in the attached technical presentation. Note: the UL certificate remains valid for this Pocan natural material as well.</p> <p>We have been using Pocan blue for more than 20 years for our Duflex & Dubox product family and we have never experienced an extreme situation like this."</p>	
Affected Parts:	(66987 / 67013 series) See Affected parts.xls file	
Effective Date of Change:	28 April ,2022	
Last Time Buy Date:		
Earliest Disty Return Date:		
Last Time Shipment Date		
Datasheet Attached?	No	
Qual/Test Data Attached?	No	
Samples Availability Date:	06-May-22	
Available Alternatives?		
Questions?	<i>Contact your local AICC Representative, or Product Manager</i>	
	<i>Shoichi.Omote / Product Manager</i>	
	<i>Shoichi.Omote @amphenol-fci.com</i>	

Note:

Customers should contact Product Manager (or their local AICC Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN22044	67013-026LF	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-027LF	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-028	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-028LF	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-029LF	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-030	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-030LF	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-031	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-031LF	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-032	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-032LF	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-033	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-033LF	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-034	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-034LF	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-035LF	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-036	MATERIAL CHANGE	April 28, 2022
PCN22044	67013-036LF	MATERIAL CHANGE	April 28, 2022

		538-58LF-FLEX 2.54
		538-58LF-FLEX 2.54
		REMOVED FROM GPS
		538-58LF-FLEX 2.54
		538-58LF-FLEX 2.54
		REMOVED FROM GPS
		538-58LF-FLEX 2.54
		REMOVED FROM GPS
		538-58LF-FLEX 2.54
		REMOVED FROM GPS
		538-58LF-FLEX 2.54
		REMOVED FROM GPS
		538-58LF-FLEX 2.54
		REMOVED FROM GPS
		538-58LF-FLEX 2.54
		538-58LF-FLEX 2.54
		REMOVED FROM GPS
		538-58LF-FLEX 2.54

1456-145600	ACTIVE
1456-145600	ACTIVE
4340-43400	TO BE REMOVED
1456-145600	ACTIVE
1456-145600	ACTIVE
4340-43400	TO BE REMOVED
1456-145600	ACTIVE
4340-43400	TO BE REMOVED
1456-145600	ACTIVE
4340-43400	TO BE REMOVED
1456-145600	ACTIVE
4340-43400	TO BE REMOVED
1456-145600	ACTIVE
4340-43400	TO BE REMOVED
1456-145600	ACTIVE
1456-145600	ACTIVE
4340-43400	TO BE REMOVED
1456-145600	ACTIVE