



August 14, 2015
APEM End of Life Notificaion
Re: P56 64-Position Coded Rotary Switches

APEM Customers,

Due to unstable output signals, APEM is ceasing the sale of P56 64-position coded rotary switches immediately.

We apologize for any inconvenience this discontinuation may cause and we are more than happy to help you find an adequate replacement.

Sincerely

A handwritten signature in black ink that reads "David Allen".

David Allen
Product Manager