



Product Change Notice

Classification of change:	Non-functional change
Products affected:	<ul style="list-style-type: none"> • A000053 Arduino Micro • A000093 Arduino Micro without headers
Description of change:	Removal of header for ICSP (J4)
Reason for change:	Optimization of the bill of materials
Expected influence on quality, reliability, and performance:	This change won't impact the quality or performance of the product. The ICSP signal can also be accessed via the lateral headers.
Schedule:	Start shipment date: May 2025
Contact information:	For questions or comments, please contact your Arduino Sales representative.

Notice

To optimize the cost of the bill of material for the Arduino Micro (A000053) and Arduino Micro without headers (A000093), the headers for the ICSP signals on the top side of the board (J4 in schematics) will be removed. This signal can be accessed via the headers on the sides of the board.

- MOSI -> 11
- MISO -> 10
- SCK ->13

This change won't have any impact on the PCB design of the documentation.