



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1017

Issue Date: 9/25/2023

Parts Affected	SLP3-150-100-F	Old Rev.	M	New Rev.	N
	SLP3-150-100-F BE				
	SLP3-150-100-F BK				
	SLP3-150-100-F GN				
	SLP3-150-100-F GY				
	SLP3-150-100-F RD				
	SLP3-150-100-F YW				
	SLP3-150-100-R		M		N
	SLP3-150-100-R BE				
	SLP3-150-100-R BK				
	SLP3-150-100-R GN				
	SLP3-150-100-R GY				
	SLP3-150-100-R RD				
	SLP3-150-100-R YW				
	SLP3-150-150-F		M		N
	SLP3-150-150-F BE				
	SLP3-150-150-F BK				
	SLP3-150-150-F GN				
	SLP3-150-150-F GY				
	SLP3-150-150-F RD				
	SLP3-150-150-F YW				
	SLP3-150-150-R		M		N
	SLP3-150-150-R BE				
	SLP3-150-150-R BK				
	SLP3-150-150-R GN				
	SLP3-150-150-R GY				
	SLP3-150-150-R RD				
	SLP3-150-150-R YW				
	SLP3-150-200-R		M		N

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1017

Issue Date: 9/25/2023

Parts Affected	SLP3-150-200-R BE	Old Rev.		New Rev.	
	SLP3-150-200-R BK				
	SLP3-150-200-R GN				
	SLP3-150-200-R GY				
	SLP3-150-200-R RD				
	SLP3-150-200-R YW				
	SLP3-150-250-F		M		N
	SLP3-150-250-F BE				
	SLP3-150-250-F BK				
	SLP3-150-250-F GN				
	SLP3-150-250-F GY				
	SLP3-150-250-F RD				
	SLP3-150-250-F YW				
	SLP3-150-250-R		M		N
	SLP3-150-250-R BE				
	SLP3-150-250-R BK				
	SLP3-150-250-R GN				
	SLP3-150-250-R GY				
	SLP3-150-250-R RD				
	SLP3-150-250-R YW				
	SLP3-150-300-F		M		N
	SLP3-150-300-F BE				
	SLP3-150-300-F BK				
	SLP3-150-300-F GN				
	SLP3-150-300-F GY				
	SLP3-150-300-F RD				
	SLP3-150-300-F YW				
	SLP3-150-300-R		M		N
	SLP3-150-300-R BE				

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1017

Issue Date: 9/25/2023

Parts Affected	Old Rev.	New Rev.
SLP3-150-300-R BK		
SLP3-150-300-R GN		
SLP3-150-300-R GY		
SLP3-150-300-R RD		
SLP3-150-300-R YW		
SLP3-150-450-R	M	N
SLP3-150-450-R BE		
SLP3-150-450-R BK		
SLP3-150-450-R GN		
SLP3-150-450-R GY		
SLP3-150-450-R RD		
SLP3-150-450-R YW		
SLP3-200-100-F	K	L
SLP3-200-100-F BE		
SLP3-200-100-F BK		
SLP3-200-100-F GN		
SLP3-200-100-F GY		
SLP3-200-100-F RD		
SLP3-200-100-F YW		
SLP3-200-100-R	K	L
SLP3-200-100-R BE		
SLP3-200-100-R BK		
SLP3-200-100-R GN		
SLP3-200-100-R GY		
SLP3-200-100-R RD		
SLP3-200-100-R YW		
SLP3-200-150-F	K	L
SLP3-200-150-F BE		
SLP3-200-150-F BK		

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1017

Issue Date: 9/25/2023

Parts Affected	SLP3-200-150-F GN	Old Rev.		New Rev.	
	SLP3-200-150-F GY				
	SLP3-200-150-F RD				
	SLP3-200-150-F YW				
	SLP3-200-150-R		K		L
	SLP3-200-150-R BE				
	SLP3-200-150-R BK				
	SLP3-200-150-R GN				
	SLP3-200-150-R GY				
	SLP3-200-150-R RD				
	SLP3-200-150-R YW				
	SLP3-200-200-R		K		L
	SLP3-200-200-R BE				
	SLP3-200-200-R BK				
	SLP3-200-200-R GN				
	SLP3-200-200-R GY				
	SLP3-200-200-R RD				
	SLP3-200-200-R YW				
	SLP3-200-250-F		K		L
	SLP3-200-250-F BE				
	SLP3-200-250-F BK				
	SLP3-200-250-F GN				
	SLP3-200-250-F GY				
	SLP3-200-250-F RD				
	SLP3-200-250-F YW				
	SLP3-250-100-F		K		L
	SLP3-250-100-F BE				
	SLP3-250-100-F BK				
	SLP3-250-100-F GN				

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1017

Issue Date: 9/25/2023

Parts Affected	Old Rev.	New Rev.
SLP3-250-100-F GY		
SLP3-250-100-F RD		
SLP3-250-100-F YW		
SLP3-250-100-R	K	L
SLP3-250-100-R BE		
SLP3-250-100-R BK		
SLP3-250-100-R GN		
SLP3-250-100-R GY		
SLP3-250-100-R RD		
SLP3-250-100-R YW		
SLP3-300-100-F	K	L
SLP3-300-100-F BE		
SLP3-300-100-F BK		
SLP3-300-100-F GN		
SLP3-300-100-F GY		
SLP3-300-100-F RD		
SLP3-300-100-F YW		
SLP3-300-100-R	K	L
SLP3-300-100-R BE		
SLP3-300-100-R BK		
SLP3-300-100-R GN		
SLP3-300-100-R GY		
SLP3-300-100-R RD		
SLP3-300-100-R YW		
SLP3-300-250-F	K	L
SLP3-300-250-F BE		
SLP3-300-250-F BK		
SLP3-300-250-F GN		
SLP3-300-250-F GY		

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1017

Issue Date: 9/25/2023

Parts Affected	Old Rev.	New Rev.
SLP3-300-250-F RD		
SLP3-300-250-F YW		
SLP3-300-250-R		
SLP3-300-250-R BE		
SLP3-300-250-R BK		
SLP3-300-250-R GN		
SLP3-300-250-R GY		
SLP3-300-250-R RD		
SLP3-300-250-R YW		
SLP3-300-450-F	K	L
SLP3-300-450-F BE		
SLP3-300-450-F BK		
SLP3-300-450-F GN		
SLP3-300-450-F GY		
SLP3-300-450-F RD		
SLP3-300-450-F YW		
SLP3-300-450-R	K	L
SLP3-300-450-R BE		
SLP3-300-450-R BK		
SLP3-300-450-R GN		
SLP3-300-450-R GY		
SLP3-300-450-R RD		
SLP3-300-450-R YW		
SLP3-350-100-F	K	L
SLP3-350-100-F BE		
SLP3-350-100-F BK		
SLP3-350-100-F GN		
SLP3-350-100-F GY		
SLP3-350-100-F RD		

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1017

Issue Date: 9/25/2023

Parts Affected	SLP3-350-100-F YW	Old Rev.		New Rev.	
	SLP3-350-100-R		K		L
	SLP3-350-100-R BE				
	SLP3-350-100-R BK				
	SLP3-350-100-R GN				
	SLP3-350-100-R GY				
	SLP3-350-100-R RD				
	SLP3-350-100-R YW				
	SLP3-350-200-F				
	SLP3-350-200-F BE				
	SLP3-350-200-F BK				
	SLP3-350-200-F GN				
	SLP3-350-200-F GY				
	SLP3-350-200-F RD				
	SLP3-350-200-F YW				
	SLP3-350-350-F		K		L
	SLP3-350-350-F BE				
	SLP3-350-350-F BK				
	SLP3-350-350-F GN				
	SLP3-350-350-F GY				
	SLP3-350-350-F RD				
	SLP3-350-350-F YW				
	SLP3-400-100-F		K		L
	SLP3-400-100-F BE				
	SLP3-400-100-F BK				
	SLP3-400-100-F GN				
	SLP3-400-100-F GY				
	SLP3-400-100-F RD				
	SLP3-400-100-F YW				

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1017

Issue Date: 9/25/2023

Parts Affected	SLP3-400-100-R	Old Rev.		New Rev.	
	SLP3-400-100-R BE				
	SLP3-400-100-R BK				
	SLP3-400-100-R GN				
	SLP3-400-100-R GY				
	SLP3-400-100-R RD				
	SLP3-400-100-R YW				
	SLP3-400-250-F				
	SLP3-400-250-F BE				
	SLP3-400-250-F BK				
	SLP3-400-250-F GN				
	SLP3-400-250-F GY				
	SLP3-400-250-F RD				
	SLP3-400-250-F YW				
	SLP3-400-450-R		K		L
	SLP3-400-450-R BE				
	SLP3-400-450-R BK				
	SLP3-400-450-R GN				
	SLP3-400-450-R GY				
	SLP3-400-450-R RD				
	SLP3-400-450-R YW				
	SLP3-450-100-F				
	SLP3-450-100-F BE				
	SLP3-450-100-F BK				
	SLP3-450-100-F GN				
	SLP3-450-100-F GY				
	SLP3-450-100-F RD				
	SLP3-450-100-F YW				
	SLP3-450-100-R		K		L

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1017

Issue Date: 9/25/2023

Parts Affected	SLP3-450-100-R BE	Old Rev.		New Rev.	
	SLP3-450-100-R BK				
	SLP3-450-100-R GN				
	SLP3-450-100-R GY				
	SLP3-450-100-R RD				
	SLP3-450-100-R YW				
	SLP3-500-100-F		K		L
	SLP3-500-100-F BE				
	SLP3-500-100-F BK				
	SLP3-500-100-F GN				
	SLP3-500-100-F GY				
	SLP3-500-100-F RD				
	SLP3-500-100-F YW				
	SLP3-500-100-R		K		L
	SLP3-500-100-R BE				
	SLP3-500-100-R BK				
	SLP3-500-100-R GN				
	SLP3-500-100-R GY				
	SLP3-500-100-R RD				
	SLP3-500-100-R YW				
	SLP3-500-250-F				
	SLP3-500-250-F BE				
	SLP3-500-250-F BK				
	SLP3-500-250-F GN				
	SLP3-500-250-F GY				
	SLP3-500-250-F RD				
	SLP3-500-250-F YW				
	SLP3-500-250-R		K		L
	SLP3-500-250-R BE				

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1017

Issue Date: 9/25/2023

Parts Affected	SLP3-500-250-R BK	Old Rev.		New Rev.	
	SLP3-500-250-R GN				
	SLP3-500-250-R GY				
	SLP3-500-250-R RD				
	SLP3-500-250-R YW				
	SLP3-500-400-R				
	SLP3-500-400-R BE				
	SLP3-500-400-R BK				
	SLP3-500-400-R GN				
	SLP3-500-400-R GY				
	SLP3-500-400-R RD				
	SLP3-500-400-R YW				
	SLP3-500-450-R		K		L
	SLP3-500-450-R BE				
	SLP3-500-450-R BK				
	SLP3-500-450-R GN				
	SLP3-500-450-R GY				
	SLP3-500-450-R RD				
	SLP3-500-450-R YW				
	SLP3-550-100-F				
	SLP3-550-100-F BE				
	SLP3-550-100-F BK				
	SLP3-550-100-F GN				
	SLP3-550-100-F GY				
	SLP3-550-100-F RD				
	SLP3-550-100-F YW				
	SLP3-550-100-R				
	SLP3-550-100-R BE				
	SLP3-550-100-R BK				

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1017

Issue Date: 9/25/2023

Parts Affected	SLP3-550-100-R GN	Old Rev.		New Rev.	
	SLP3-550-100-R GY				
	SLP3-550-100-R RD				
	SLP3-550-100-R YW				
	SLP3-600-100-F				
	SLP3-600-100-F BE				
	SLP3-600-100-F BK				
	SLP3-600-100-F GN				
	SLP3-600-100-F GY				
	SLP3-600-100-F RD				
	SLP3-600-100-F YW				
	SLP3-600-100-R				
	SLP3-600-100-R BE				
	SLP3-600-100-R BK				
	SLP3-600-100-R GN				
	SLP3-600-100-R GY				
	SLP3-600-100-R RD				
	SLP3-600-100-R YW				
	SLP3-600-450-R		K		L
	SLP3-600-450-R BE				
	SLP3-600-450-R BK				
	SLP3-600-450-R GN				
	SLP3-600-450-R GY				
	SLP3-600-450-R RD				
	SLP3-600-450-R YW				
	SLP3-650-100-F				
	SLP3-650-100-F BE				
	SLP3-650-100-F BK				
	SLP3-650-100-F GN				

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1017

Issue Date: 9/25/2023

Parts Affected	Old Rev.	New Rev.
SLP3-650-100-F GY		
SLP3-650-100-F RD		
SLP3-650-100-F YW		
SLP3-650-100-R		
SLP3-650-100-R BE		
SLP3-650-100-R BK		
SLP3-650-100-R GN		
SLP3-650-100-R GY		
SLP3-650-100-R RD		
SLP3-650-100-R YW		
SLP3-700-100-F		
SLP3-700-100-F BE		
SLP3-700-100-F BK		
SLP3-700-100-F GN		
SLP3-700-100-F GY		
SLP3-700-100-F RD		
SLP3-700-100-F YW		
SLP3-700-100-R		
SLP3-700-100-R BE		
SLP3-700-100-R BK		
SLP3-700-100-R GN		
SLP3-700-100-R GY		
SLP3-700-100-R RD		
SLP3-700-100-R YW		
SLP3-700-450-R	K	L
SLP3-700-450-R BE		
SLP3-700-450-R BK		
SLP3-700-450-R GN		
SLP3-700-450-R GY		

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1017

Issue Date: 9/25/2023

Parts Affected	SLP3-700-450-R RD	Old Rev.		New Rev.	
	SLP3-700-450-R YW				

Change Will Affect:

The Recommended Mounting Holes

Description of Change:

The recommended mounting holes changed from .046 +.003/-.002 in to .048in ~ .052in.

Effective Date of Change: September 25, 2023

Reason for Change: Changing mounting holes recommendation for better fit.

Updated on October 16, 2023. The update was implemented to address a typographical error.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122