



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1047

Issue Date: 7/16/2024

Parts Affected	Old Rev.	New Rev.
FLP25-1.900	D	E
FLP25-1.950	D	E
FLP25-10.0	D	E
FLP25-12.0	D	E
FLP25-13.0	D	E
FLP25-13.5	D	E
FLP25-144.00	D	E
FLP25-16.0	D	E
FLP25-17.0	D	E
FLP25-2.0	D	E
FLP25-2.325	D	E
FLP25-2.375	D	E
FLP25-20.83	D	E
FLP25-3.315	D	E
FLP25-3.5	D	E
FLP25-3.735	D	E
FLP25-4.0	D	E
FLP25-4.5	D	E
FLP25-40.0	D	E
FLP25-5.0	D	E
FLP25-5.315	D	E
FLP25-6.0	D	E
FLP25-8.0	D	E
PM7-C2031-10.00	B	C
PM7-C2031-18.00	B	C
PM7-C2031-2.00	B	C
PM7-C2031-2.50	B	C
PM7-C2031-20.00	B	C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1047

Issue Date: 7/16/2024

Parts Affected		Old Rev.	New Rev.
	SMFLP25-1.00	D	E
	SMFLP25-10.0	D	E
	SMFLP25-12.0	D	E
	SMFLP25-16.0	D	E
	SMFLP25-2.5	D	E
	SMFLP25-3.0	D	E
	SMFLP25-3.5	D	E
	SMFLP25-4.0	D	E
	SMFLP25-5.0	D	E
	SMFLP25-5.5	D	E
	SMFLP25-6.0	D	E
	SMFLP25-60.0	D	E
	SMFLP25-7.0	D	E
	SMFLP25-8.0	D	E
	SMFLP25-8.5	D	E
	FLP25-23.0	D	E

Change Will Affect:

The change will affect the product specifications.

Description of Change:

The drawings for FLP25-XX.X, PM7-C2031-XX.XX, and SMFLP25-X.X have been revised to remove incorrect and unnecessary dimensions.

Effective Date of Change: July 16, 2024

Reason for Change: Typographical errors on the datasheets.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122