



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1055

Issue Date: 8/13/2024

Parts Affected		Old Rev.	New Rev.
	PM5BWC	F	G
	PM5BWD	F	G
	PM5GC	F	G
	PM5GD	F	G
	PM5YD	F	G
	PM5AD	F	G
	PM5HC	F	G
	PM5HD	F	G
	PM5RD	F	G
	PM5BC	F	G
	PM5SYD	F	G
	PM5SRD	F	G
	PM5GDL	F	G
	PM5YDL	F	G
	PM5HDL	F	G
	PM5AD	F	G
	PM5BC	F	G
	PM5BWC	F	G
	PM5BWD	F	G
	PM5GC	F	G
	PM5GD	F	G
	PM5GDL	F	G
	PM5HC	F	G
	PM5HD	F	G
	PM5HDL	F	G
	PM5RD	F	G
	PM5SRD	F	G
	PM5SYD	F	G
	PM5YD	F	G

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1055

Issue Date: 8/13/2024

Parts Affected	PM5YDL	Old Rev.	F	New Rev.	G
----------------	--------	----------	---	----------	---

### Change Will Affect:

This change will affect the product specifications.

### Description of Change:

The distance from the shortest lead to the longest lead on the drawing has been updated from .040 [1.0mm] to .04 [1.0mm] MIN.

**Effective Date of Change:** August 13, 2024

**Reason for Change:** Typographical error in the datasheet.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122