



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1064

Issue Date: 9/4/2024

Parts Affected		Old Rev.	F	New Rev.	G
	SLM-150		F		G
	SLM-160		F		G
	SLM-170		F		G
	SLM-180		F		G
	SLM-190		F		G
	SLM-200		F		G
	SLM-210		F		G
	SLM-220		F		G
	SLM-230		F		G
	SLM-240		F		G
	SLM-250		F		G
	SLM-260		F		G
	SLM-270		F		G
	SLM-280		F		G
	SLM-290		F		G
	SLM-300		F		G
	SLM-310		F		G
	SLM-320		F		G
	SLM-330		F		G
	SLM-340		F		G
	SLM-350		F		G
	SLM-360		F		G
	SLM-370		F		G
	SLM-380		F		G
	SLM-390		F		G
	SLM-400		F		G
	SLM-410		F		G
	SLM-420		F		G

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1064

Issue Date: 9/4/2024

Parts Affected	SLM-430	Old Rev.	F	New Rev.	G
	SLM-440		F		G
	SLM-450		F		G
	SLM-470		F		G
	SLM-490		F		G
	SLM-510		F		G
	SLM-530		F		G
	SLM-550		F		G
	SLM-570		F		G
	SLM-590		F		G
	SLM-610		F		G
	SLM-630		F		G
	SLM-650		F		G
	SLM-670		F		G
	SLM-690		F		G
	SLM-710		F		G
	SLM-730		F		G
	SLM-750		F		G
	SLM-770		F		G
	SLM-790		F		G
	SLM-810		F		G
	SLM-830		F		G
	SLM-850		F		G
	SLM-870		F		G
	SLM-890		F		G

Change Will Affect:

This change will affect the product specifications.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1064

Issue Date: 9/4/2024

Description of Change:

The .100" hole pitch dimension was changed to be a reference value.

Effective Date of Change: September 4, 2024

Reason for Change: Typographical error in the datasheet.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122