



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	LC4-1.950-F7P	Old Rev.	C	New Rev.	D
	LC4-1.950-F7P-2		C		D
	LC4-1.950-F7P-4		C		D
	LC4-1.950-F7P-5		C		D
	LC4-1.950-F7P-6		C		D
	LC4-1.950-F7P-9		C		D
	LC4-10.0-F7P		C		D
	LC4-10.0-F7P-2		C		D
	LC4-10.0-F7P-4		C		D
	LC4-10.0-F7P-5		C		D
	LC4-10.0-F7P-6		C		D
	LC4-10.0-F7P-9		C		D
	LC4-2.0-F7P		C		D
	LC4-2.0-F7P-2		C		D
	LC4-2.0-F7P-4		C		D
	LC4-2.0-F7P-5		C		D
	LC4-2.0-F7P-6		C		D
	LC4-2.0-F7P-9		C		D
	LC4-2.375-F7P		C		D
	LC4-2.375-F7P-2		C		D
	LC4-2.375-F7P-4		C		D
	LC4-2.375-F7P-5		C		D
	LC4-2.375-F7P-6		C		D
	LC4-2.375-F7P-9		C		D
	LC4-3.5-F7P		C		D
	LC4-3.5-F7P-2		C		D
	LC4-3.5-F7P-4		C		D
	LC4-3.5-F7P-5		C		D
	LC4-3.5-F7P-6		C		D

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	LC4-3.5-F7P-9	Old Rev.	C	New Rev.	D
	LC4-6.0-F7P		C		D
	LC4-6.0-F7P-2		C		D
	LC4-6.0-F7P-4		C		D
	LC4-6.0-F7P-5		C		D
	LC4-6.0-F7P-6		C		D
	LC4-6.0-F7P-9		C		D
	LC4-8.0-F7P		C		D
	LC4-8.0-F7P-2		C		D
	LC4-8.0-F7P-4		C		D
	LC4-8.0-F7P-5		C		D
	LC4-8.0-F7P-6		C		D
	LC4-8.0-F7P-9		C		D
	FLP25R10.0-SA		G		H
	FLP25R13.0-SG		G		H
	FLP25R13.0-SR		G		H
	FLP25R24.0-SG		G		H
	FLP25R24.0-SUG		G		H
	FLP25R24.0-UG		G		H
	FLP25R3.5-UBW		G		H
	FLP25R4.5-SUR		G		H
	FLP25R4.5-UR		G		H
	FLP25R5.0-SBC		G		H
	FLP25R5.0-SUR		G		H
	FLP25R6.0-SA		G		H
	FLP25R6.0-SUG		G		H
	FLP25R6.0-SUR		G		H
	FLP25R6.0-UBW		G		H
	FLP25R6.0-UW		G		H

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	FLP25R6.5-SA	Old Rev.	G	New Rev.	H
	FLP25R6.5-SUG		G		H
	FLP25R6.5-SUR		G		H
	FLP25R6.5-UBW		G		H
	FLP25R6.5-UW		G		H
	FLP25R60.0-UBW		G		H
	FLP25R8.0-SG		G		H
	FLP25R9.5-SUG		G		H
	FLP25V10.0-BC		G		H
	FLP25V10.0-SBC		G		H
	FLP25V13.0-SG		G		H
	FLP25V13.0-SR		G		H
	FLP25V2.0-SA		G		H
	FLP25V2.0-SUG		G		H
	FLP25V2.0-SUR		G		H
	FLP25V2.0-UBW		G		H
	FLP25V3.0-SA		G		H
	FLP25V3.0-SUG		G		H
	FLP25V3.0-SUR		G		H
	FLP25V4.0-BC		G		H
	FLP25V4.0-SBC		G		H
	FLP25V4.0-SG		G		H
	FLP25V40.0-UW		G		H
	FLP25V6.0-BC		G		H
	FLP25V6.0-SA		G		H
	FLP25V6.0-SG		G		H
	FLP25V6.0-SUG		G		H
	FLP25V6.0-SUR		G		H
	FLP25V6.0-UBW		G		H

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	FLP25V6.0-UW	Old Rev.	G	New Rev.	H
	FLP25V8.0-UW		G		H
	FLP25V9.0-BC		G		H
	FR4-13.0-SG-F7P		A		B
	FR4-13.0-SG-F7P-2		A		B
	FR4-13.0-SG-F7P-4		A		B
	FR4-13.0-SG-F7P-5		A		B
	FR4-13.0-SG-F7P-6		A		B
	FR4-13.0-SG-F7P-9		A		B
	FR4-13.0-SR-F7P		A		B
	FR4-13.0-SR-F7P-2		A		B
	FR4-13.0-SR-F7P-4		A		B
	FR4-13.0-SR-F7P-5		A		B
	FR4-13.0-SR-F7P-6		A		B
	FR4-13.0-SR-F7P-9		A		B
	FR4-3.5-UBW-F7P		A		B
	FR4-3.5-UBW-F7P-2		A		B
	FR4-3.5-UBW-F7P-4		A		B
	FR4-3.5-UBW-F7P-5		A		B
	FR4-3.5-UBW-F7P-6		A		B
	FR4-3.5-UBW-F7P-9		A		B
	FR4-5.0-SUR-F7P		A		B
	FR4-5.0-SUR-F7P-2		A		B
	FR4-5.0-SUR-F7P-4		A		B
	FR4-5.0-SUR-F7P-5		A		B
	FR4-5.0-SUR-F7P-6		A		B
	FR4-5.0-SUR-F7P-9		A		B
	FR4-6.0-SA-F7P		A		B
	FR4-6.0-SA-F7P-2		A		B

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	FR4-6.0-SA-F7P-4	Old Rev.	A	New Rev.	B
	FR4-6.0-SA-F7P-5		A		B
	FR4-6.0-SA-F7P-6		A		B
	FR4-6.0-SA-F7P-9		A		B
	FR4-6.0-SUG-F7P		A		B
	FR4-6.0-SUG-F7P-2		A		B
	FR4-6.0-SUG-F7P-4		A		B
	FR4-6.0-SUG-F7P-5		A		B
	FR4-6.0-SUG-F7P-6		A		B
	FR4-6.0-SUG-F7P-9		A		B
	FR4-6.0-SUR-F7P		A		B
	FR4-6.0-SUR-F7P-2		A		B
	FR4-6.0-SUR-F7P-4		A		B
	FR4-6.0-SUR-F7P-5		A		B
	FR4-6.0-SUR-F7P-6		A		B
	FR4-6.0-SUR-F7P-9		A		B
	FR4-6.0-UBW-F7P		A		B
	FR4-6.0-UBW-F7P-2		A		B
	FR4-6.0-UBW-F7P-4		A		B
	FR4-6.0-UBW-F7P-5		A		B
	FR4-6.0-UBW-F7P-6		A		B
	FR4-6.0-UBW-F7P-9		A		B
	FR4-6.5-SA-F7P		A		B
	FR4-6.5-SA-F7P-2		A		B
	FR4-6.5-SA-F7P-4		A		B
	FR4-6.5-SA-F7P-5		A		B
	FR4-6.5-SA-F7P-6		A		B
	FR4-6.5-SA-F7P-9		A		B
	FR4-6.5-SUG-F7P		A		B

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected		Old Rev.		New Rev.	
	FR4-6.5-SUG-F7P-2		A		B
	FR4-6.5-SUG-F7P-4		A		B
	FR4-6.5-SUG-F7P-5		A		B
	FR4-6.5-SUG-F7P-6		A		B
	FR4-6.5-SUG-F7P-9		A		B
	FR4-6.5-SUR-F7P		A		B
	FR4-6.5-SUR-F7P-2		A		B
	FR4-6.5-SUR-F7P-4		A		B
	FR4-6.5-SUR-F7P-5		A		B
	FR4-6.5-SUR-F7P-6		A		B
	FR4-6.5-SUR-F7P-9		A		B
	FR4-6.5-UBW-F7P		A		B
	FR4-6.5-UBW-F7P-2		A		B
	FR4-6.5-UBW-F7P-4		A		B
	FR4-6.5-UBW-F7P-5		A		B
	FR4-6.5-UBW-F7P-6		A		B
	FR4-6.5-UBW-F7P-9		A		B
	FV4-13.0-SG-F7P		A		B
	FV4-13.0-SG-F7P-2		A		B
	FV4-13.0-SG-F7P-4		A		B
	FV4-13.0-SG-F7P-5		A		B
	FV4-13.0-SG-F7P-6		A		B
	FV4-13.0-SG-F7P-9		A		B
	FV4-13.0-SR-F7P		A		B
	FV4-13.0-SR-F7P-2		A		B
	FV4-13.0-SR-F7P-4		A		B
	FV4-13.0-SR-F7P-5		A		B
	FV4-13.0-SR-F7P-6		A		B
	FV4-13.0-SR-F7P-9		A		B

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	FV4-2.0-UBW-F7P	Old Rev.	A	New Rev.	B
	FV4-2.0-UBW-F7P-2		A		B
	FV4-2.0-UBW-F7P-4		A		B
	FV4-2.0-UBW-F7P-5		A		B
	FV4-2.0-UBW-F7P-6		A		B
	FV4-2.0-UBW-F7P-9		A		B
	FV4-4.0-SBC-F7P		A		B
	FV4-4.0-SBC-F7P-2		A		B
	FV4-4.0-SBC-F7P-4		A		B
	FV4-4.0-SBC-F7P-5		A		B
	FV4-4.0-SBC-F7P-6		A		B
	FV4-4.0-SBC-F7P-9		A		B
	FV4-6.0-SA-F7P		A		B
	FV4-6.0-SA-F7P-2		A		B
	FV4-6.0-SA-F7P-4		A		B
	FV4-6.0-SA-F7P-5		A		B
	FV4-6.0-SA-F7P-6		A		B
	FV4-6.0-SA-F7P-9		A		B
	FV4-6.0-SUG-F7P		A		B
	FV4-6.0-SUG-F7P-2		A		B
	FV4-6.0-SUG-F7P-4		A		B
	FV4-6.0-SUG-F7P-5		A		B
	FV4-6.0-SUG-F7P-6		A		B
	FV4-6.0-SUG-F7P-9		A		B
	FV4-6.0-SUR-F7P		A		B
	FV4-6.0-SUR-F7P-2		A		B
	FV4-6.0-SUR-F7P-4		A		B
	FV4-6.0-SUR-F7P-5		A		B
	FV4-6.0-SUR-F7P-6		A		B

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected		Old Rev.	A	New Rev.	B
	FV4-6.0-SUR-F7P-9		A		B
	FV4-6.0-UBW-F7P		A		B
	FV4-6.0-UBW-F7P-2		A		B
	FV4-6.0-UBW-F7P-4		A		B
	FV4-6.0-UBW-F7P-5		A		B
	FV4-6.0-UBW-F7P-6		A		B
	FV4-6.0-UBW-F7P-9		A		B
	OR4-2.3-RGB-F7P		B		C
	OR4-2.3-RGB-F7P-2		B		C
	OR4-2.3-RGB-F7P-4		B		C
	OR4-2.3-RGB-F7P-5		B		C
	OR4-2.3-RGB-F7P-6		B		C
	OR4-2.3-RGB-F7P-9		B		C
	OR4-2.75-RGB-F7P		B		C
	OR4-2.75-RGB-F7P-2		B		C
	OR4-2.75-RGB-F7P-4		B		C
	OR4-2.75-RGB-F7P-5		B		C
	OR4-2.75-RGB-F7P-6		B		C
	OR4-2.75-RGB-F7P-9		B		C
	OR4-4.0-WHT-F7P		B		C
	OR4-4.0-WHT-F7P-2		B		C
	OR4-4.0-WHT-F7P-4		B		C
	OR4-4.0-WHT-F7P-5		B		C
	OR4-4.0-WHT-F7P-6		B		C
	OR4-4.0-WHT-F7P-9		B		C
	OR4-6.0-WHT-F7P		B		C
	OR4-6.0-WHT-F7P-2		B		C
	OR4-6.0-WHT-F7P-4		B		C
	OR4-6.0-WHT-F7P-5		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	OR4-6.0-WHT-F7P-6	Old Rev.	B	New Rev.	C
	OR4-6.0-WHT-F7P-9		B		C
	R25-2.3-RGB		D		E
	R25-2.75-RGB		D		E
	R25-4.0-WHT		D		E
	R25-5.0-RGB		D		E
	R25-6.0-WHT		D		E

Change Will Affect:

This change will affect the product specifications.

Description of Change:

The drawing views and dimensions of the assembly product have been adjusted due to the updated lens cap component used. (c.f. new dimension on the drawing)

Effective Date of Change: October 3, 2024

Reason for Change: The changes made to the lens cap were intended to enhance the product's performance and quality.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122