



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1073

Issue Date: 11/1/2024

Parts Affected		Old Rev.		New Rev.	
	SASG3-12.00-RGB		F		G
	SASG3-18.00-RGB		F		G
	SASG3-24.00-RGB		F		G
	SASG3-6.00-RGB		F		G
	SASG4-12.00-RGB		F		G
	SASG4-18.00-RGB		F		G
	SASG4-24.00-RGB		F		G
	SASG4-6.00-RGB		F		G
	SASG5-12.00-RGB		E		F
	SASG5-18.00-RGB		E		F
	SASG5-24.00-RGB		E		F
	SASG5-6.00-RGB		E		F

**Change Will Affect:**

The product fit.

**Description of Change:**

The light engine has been redesigned to optimize the cable system, reducing the number of cables from 5 to 4. Additionally, PCBA components have been repositioned to the top side of the PCB only. These modifications do not compromise the product's performance or light output.

**Effective Date of Change:** November 1, 2024

**Reason for Change:** The changes made to the PCBA were part of Bivar commitment to continuous improvement, intended to create a more effective and simpler design.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122