



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1085

Issue Date: 3/21/2025

Parts Affected		Old Rev.	A	New Rev.	B
	UHF3-0.250-N-67				
	UHF3-0.500-N-67		A		B
	UHF3-0.500-Y-67		A		B
	UHF3-0.750-Y-67		A		B
	UHF3-1.000-Y-67		A		B
	UHF3-1.250-Y-67		A		B
	UHF3-1.500-Y-67		A		B
	UHF3-1.750-Y-67		A		B
	UHF3-2.000-Y-67		A		B
	UHF3-2.500-Y-67		A		B
	UHF3-3.000-Y-67		A		B
	UHF3-3.500-Y-67		A		B
	UHF3-4.000-Y-67		A		B
	UHF3-4.500-Y-67		A		B
	UHF3-5.000-Y-67		A		B
	UHF3-5.500-Y-67		A		B
	UHF3-6.000-Y-67		A		B
	UHF4-0.250-N-67		A		B
	UHF4-0.500-N-67		A		B
	UHF4-0.500-Y-67		A		B
	UHF4-0.750-N-67		A		B
	UHF4-0.750-Y-67		A		B
	UHF4-1.000-Y-67		A		B
	UHF4-1.250-Y-67		A		B
	UHF4-1.500-Y-67		A		B
	UHF4-1.750-Y-67		A		B
	UHF4-2.000-Y-67		A		B
	UHF4-2.500-Y-67		A		B
	UHF4-3.000-Y-67		A		B

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1085

Issue Date: 3/21/2025

Parts Affected		Old Rev.	A	New Rev.	B
	UHF4-3.500-Y-67				
	UHF4-4.000-Y-67		A		B
	UHF4-4.500-Y-67		A		B
	UHF4-5.000-Y-67		A		B
	UHF4-5.500-Y-67		A		B
	UHF4-6.000-Y-67		A		B
	UHF5-0.250-N-67		A		B
	UHF5-0.500-N-67		A		B
	UHF5-0.500-Y-67		A		B
	UHF5-0.750-N-67		A		B
	UHF5-0.750-Y-67		A		B
	UHF5-1.000-N-67		A		B
	UHF5-1.000-Y-67		A		B
	UHF5-1.250-N-67		A		B
	UHF5-1.250-Y-67		A		B
	UHF5-1.500-Y-67		A		B
	UHF5-1.750-Y-67		A		B
	UHF5-2.000-Y-67		A		B
	UHF5-2.500-Y-67		A		B
	UHF5-3.000-Y-67		A		B
	UHF5-3.500-Y-67		A		B
	UHF5-4.000-Y-67		A		B
	UHF5-4.500-Y-67		A		B
	UHF5-5.000-Y-67		A		B
	UHF5-5.500-Y-67		A		B
	UHF5-6.000-Y-67		A		B

**Change Will Affect:**

This change will affect the product specifications.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1085

Issue Date: 3/21/2025

### Description of Change:

The drawing has been revised as follows:

- The adapter pocket height has been included (refer to drawing).
- The minimum custom length has been updated from 0.100" to 0.250".

**Effective Date of Change:** March 21, 2025

**Reason for Change:** Clarification of product specifications.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122