



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ2-100	Old Rev.	B	New Rev.	C
	PLPQ2-100 BE		B		C
	PLPQ2-100 BK		B		C
	PLPQ2-100 GN		B		C
	PLPQ2-100 GY		B		EOL
	PLPQ2-100 RD		B		C
	PLPQ2-100 YW		B		C
	PLPQ2-100-FF		B		C
	PLPQ2-100-FF BE		B		C
	PLPQ2-100-FF BK		B		C
	PLPQ2-100-FF GN		B		C
	PLPQ2-100-FF GY		B		EOL
	PLPQ2-100-FF RD		B		C
	PLPQ2-100-FF YW		B		C
	PLPQ2-10MM		B		C
	PLPQ2-10MM BE		B		C
	PLPQ2-10MM BK		B		C
	PLPQ2-10MM GN		B		C
	PLPQ2-10MM GY		B		EOL
	PLPQ2-10MM RD		B		C
	PLPQ2-10MM YW		B		C
	PLPQ2-10MM-FF		B		C
	PLPQ2-10MM-FF BE		B		C
	PLPQ2-10MM-FF BK		B		C
	PLPQ2-10MM-FF GN		B		C
	PLPQ2-10MM-FF GY		B		EOL
	PLPQ2-10MM-FF RD		B		C
	PLPQ2-10MM-FF YW		B		C
	PLPQ2-125		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ2-125 BE	Old Rev.	B	New Rev.	C
	PLPQ2-125 BK		B		C
	PLPQ2-125 GN		B		C
	PLPQ2-125 GY		B		EOL
	PLPQ2-125 RD		B		C
	PLPQ2-125 YW		B		C
	PLPQ2-125-FF		B		C
	PLPQ2-125-FF BE		B		C
	PLPQ2-125-FF BK		B		C
	PLPQ2-125-FF GN		B		C
	PLPQ2-125-FF GY		B		EOL
	PLPQ2-125-FF RD		B		C
	PLPQ2-125-FF YW		B		C
	PLPQ2-188		B		C
	PLPQ2-188 BE		B		C
	PLPQ2-188 BK		B		C
	PLPQ2-188 GN		B		C
	PLPQ2-188 GY		B		EOL
	PLPQ2-188 RD		B		C
	PLPQ2-188 YW		B		C
	PLPQ2-188-FF		B		C
	PLPQ2-188-FF BE		B		C
	PLPQ2-188-FF BK		B		C
	PLPQ2-188-FF GN		B		C
	PLPQ2-188-FF GY		B		EOL
	PLPQ2-188-FF RD		B		C
	PLPQ2-188-FF YW		B		C
	PLPQ2-250		B		C
	PLPQ2-250 BE		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ2-250 BK	Old Rev.	B	New Rev.	C
	PLPQ2-250 GN		B		C
	PLPQ2-250 GY		B		EOL
	PLPQ2-250 RD		B		C
	PLPQ2-250 YW		B		C
	PLPQ2-250-FF		B		C
	PLPQ2-250-FF BE		B		C
	PLPQ2-250-FF BK		B		C
	PLPQ2-250-FF GN		B		C
	PLPQ2-250-FF GY		B		EOL
	PLPQ2-250-FF RD		B		C
	PLPQ2-250-FF YW		B		C
	PLPQ2-313		B		C
	PLPQ2-313 BE		B		C
	PLPQ2-313 BK		B		C
	PLPQ2-313 GN		B		C
	PLPQ2-313 GY		B		EOL
	PLPQ2-313 RD		B		C
	PLPQ2-313 YW		B		C
	PLPQ2-313-FF		B		C
	PLPQ2-313-FF BE		B		C
	PLPQ2-313-FF BK		B		C
	PLPQ2-313-FF GN		B		C
	PLPQ2-313-FF GY		B		EOL
	PLPQ2-313-FF RD		B		C
	PLPQ2-313-FF YW		B		C
	PLPQ2-375		B		C
	PLPQ2-375 BE		B		C
	PLPQ2-375 BK		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ2-375 GN	Old Rev.	B	New Rev.	C
	PLPQ2-375 GY		B		EOL
	PLPQ2-375 RD		B		C
	PLPQ2-375 YW		B		C
	PLPQ2-375-FF		B		C
	PLPQ2-375-FF BE		B		C
	PLPQ2-375-FF BK		B		C
	PLPQ2-375-FF GN		B		C
	PLPQ2-375-FF GY		B		EOL
	PLPQ2-375-FF RD		B		C
	PLPQ2-375-FF YW		B		C
	PLPQ2-3MM		B		C
	PLPQ2-3MM BE		B		C
	PLPQ2-3MM BK		B		C
	PLPQ2-3MM GN		B		C
	PLPQ2-3MM GY		B		EOL
	PLPQ2-3MM RD		B		C
	PLPQ2-3MM YW		B		C
	PLPQ2-3MM-FF		B		C
	PLPQ2-3MM-FF BE		B		C
	PLPQ2-3MM-FF BK		B		C
	PLPQ2-3MM-FF GN		B		C
	PLPQ2-3MM-FF GY		B		EOL
	PLPQ2-3MM-FF RD		B		C
	PLPQ2-3MM-FF YW		B		C
	PLPQ2-4MM		B		C
	PLPQ2-4MM BE		B		C
	PLPQ2-4MM BK		B		C
	PLPQ2-4MM GN		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected		Old Rev.		New Rev.	EOL
	PLPQ2-4MM GY		B		
	PLPQ2-4MM RD		B		C
	PLPQ2-4MM YW		B		C
	PLPQ2-4MM-FF		B		C
	PLPQ2-4MM-FF BE		B		C
	PLPQ2-4MM-FF BK		B		C
	PLPQ2-4MM-FF GN		B		C
	PLPQ2-4MM-FF GY		B		EOL
	PLPQ2-4MM-FF RD		B		C
	PLPQ2-4MM-FF YW		B		C
	PLPQ2-500		B		C
	PLPQ2-500 BE		B		C
	PLPQ2-500 BK		B		C
	PLPQ2-500 GN		B		C
	PLPQ2-500 GY		B		EOL
	PLPQ2-500 RD		B		C
	PLPQ2-500 YW		B		C
	PLPQ2-500-FF		B		C
	PLPQ2-500-FF BE		B		C
	PLPQ2-500-FF BK		B		C
	PLPQ2-500-FF GN		B		C
	PLPQ2-500-FF GY		B		EOL
	PLPQ2-500-FF RD		B		C
	PLPQ2-500-FF YW		B		C
	PLPQ2-5MM		B		C
	PLPQ2-5MM BE		B		C
	PLPQ2-5MM BK		B		C
	PLPQ2-5MM GN		B		C
	PLPQ2-5MM GY		B		EOL

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ2-5MM RD	Old Rev.	B	New Rev.	C
	PLPQ2-5MM YW		B		C
	PLPQ2-5MM-FF		B		C
	PLPQ2-5MM-FF BE		B		C
	PLPQ2-5MM-FF BK		B		C
	PLPQ2-5MM-FF GN		B		C
	PLPQ2-5MM-FF GY		B		EOL
	PLPQ2-5MM-FF RD		B		C
	PLPQ2-5MM-FF YW		B		C
	PLPQ2-6MM		B		C
	PLPQ2-6MM BE		B		C
	PLPQ2-6MM BK		B		C
	PLPQ2-6MM GN		B		C
	PLPQ2-6MM GY		B		EOL
	PLPQ2-6MM RD		B		C
	PLPQ2-6MM YW		B		C
	PLPQ2-6MM-FF		B		C
	PLPQ2-6MM-FF BE		B		C
	PLPQ2-6MM-FF BK		B		C
	PLPQ2-6MM-FF GN		B		C
	PLPQ2-6MM-FF GY		B		EOL
	PLPQ2-6MM-FF RD		B		C
	PLPQ2-6MM-FF YW		B		C
	PLPQ2-7MM		B		C
	PLPQ2-7MM BE		B		C
	PLPQ2-7MM BK		B		C
	PLPQ2-7MM GN		B		C
	PLPQ2-7MM GY		B		EOL
	PLPQ2-7MM RD		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ2-7MM YW	Old Rev.	B	New Rev.	C
	PLPQ2-7MM-FF		B		C
	PLPQ2-7MM-FF BE		B		C
	PLPQ2-7MM-FF BK		B		C
	PLPQ2-7MM-FF GN		B		C
	PLPQ2-7MM-FF GY		B		EOL
	PLPQ2-7MM-FF RD		B		C
	PLPQ2-7MM-FF YW		B		C
	PLPQ2-8MM		B		C
	PLPQ2-8MM BE		B		C
	PLPQ2-8MM BK		B		C
	PLPQ2-8MM GN		B		C
	PLPQ2-8MM GY		B		EOL
	PLPQ2-8MM RD		B		C
	PLPQ2-8MM YW		B		C
	PLPQ2-8MM-FF		B		C
	PLPQ2-8MM-FF BE		B		C
	PLPQ2-8MM-FF BK		B		C
	PLPQ2-8MM-FF GN		B		C
	PLPQ2-8MM-FF GY		B		EOL
	PLPQ2-8MM-FF RD		B		C
	PLPQ2-8MM-FF YW		B		C
	PLPQ2-9MM		B		C
	PLPQ2-9MM BE		B		C
	PLPQ2-9MM BK		B		C
	PLPQ2-9MM GN		B		C
	PLPQ2-9MM GY		B		EOL
	PLPQ2-9MM RD		B		C
	PLPQ2-9MM YW		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ2-9MM-FF	Old Rev.	B	New Rev.	C
	PLPQ2-9MM-FF BE		B		C
	PLPQ2-9MM-FF BK		B		C
	PLPQ2-9MM-FF GN		B		C
	PLPQ2-9MM-FF GY		B		EOL
	PLPQ2-9MM-FF RD		B		C
	PLPQ2-9MM-FF YW		B		C
	PLPQ3-100		B		C
	PLPQ3-100 BE		B		C
	PLPQ3-100 BK		B		C
	PLPQ3-100 GN		B		C
	PLPQ3-100 GY		B		EOL
	PLPQ3-100 RD		B		C
	PLPQ3-100 YW		B		C
	PLPQ3-100-FF		B		C
	PLPQ3-100-FF BE		B		C
	PLPQ3-100-FF BK		B		C
	PLPQ3-100-FF GN		B		C
	PLPQ3-100-FF GY		B		EOL
	PLPQ3-100-FF RD		B		C
	PLPQ3-100-FF YW		B		C
	PLPQ3-10MM		B		C
	PLPQ3-10MM BE		B		C
	PLPQ3-10MM BK		B		C
	PLPQ3-10MM GN		B		C
	PLPQ3-10MM GY		B		EOL
	PLPQ3-10MM RD		B		C
	PLPQ3-10MM YW		B		C
	PLPQ3-10MM-FF		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ3-10MM-FF BE	Old Rev.	B	New Rev.	C
	PLPQ3-10MM-FF BK		B		C
	PLPQ3-10MM-FF GN		B		C
	PLPQ3-10MM-FF GY		B		EOL
	PLPQ3-10MM-FF RD		B		C
	PLPQ3-10MM-FF YW		B		C
	PLPQ3-125		B		C
	PLPQ3-125 BE		B		C
	PLPQ3-125 BK		B		C
	PLPQ3-125 GN		B		C
	PLPQ3-125 GY		B		EOL
	PLPQ3-125 RD		B		C
	PLPQ3-125 YW		B		C
	PLPQ3-125-FF		B		C
	PLPQ3-125-FF BE		B		C
	PLPQ3-125-FF BK		B		C
	PLPQ3-125-FF GN		B		C
	PLPQ3-125-FF GY		B		EOL
	PLPQ3-125-FF RD		B		C
	PLPQ3-125-FF YW		B		C
	PLPQ3-188		B		C
	PLPQ3-188 BE		B		C
	PLPQ3-188 BK		B		C
	PLPQ3-188 GN		B		C
	PLPQ3-188 GY		B		EOL
	PLPQ3-188 RD		B		C
	PLPQ3-188 YW		B		C
	PLPQ3-188-FF		B		C
	PLPQ3-188-FF BE		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ3-188-FF BK	Old Rev.	B	New Rev.	C
	PLPQ3-188-FF GN		B		C
	PLPQ3-188-FF GY		B		EOL
	PLPQ3-188-FF RD		B		C
	PLPQ3-188-FF YW		B		C
	PLPQ3-250		B		C
	PLPQ3-250 BE		B		C
	PLPQ3-250 BK		B		C
	PLPQ3-250 GN		B		C
	PLPQ3-250 GY		B		EOL
	PLPQ3-250 RD		B		C
	PLPQ3-250 YW		B		C
	PLPQ3-250-FF		B		C
	PLPQ3-250-FF BE		B		C
	PLPQ3-250-FF BK		B		C
	PLPQ3-250-FF GN		B		C
	PLPQ3-250-FF GY		B		EOL
	PLPQ3-250-FF RD		B		C
	PLPQ3-250-FF YW		B		C
	PLPQ3-313		B		C
	PLPQ3-313 BE		B		C
	PLPQ3-313 BK		B		C
	PLPQ3-313 GN		B		C
	PLPQ3-313 GY		B		EOL
	PLPQ3-313 RD		B		C
	PLPQ3-313 YW		B		C
	PLPQ3-313-FF		B		C
	PLPQ3-313-FF BE		B		C
	PLPQ3-313-FF BK		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ3-313-FF GN	Old Rev.	B	New Rev.	C
	PLPQ3-313-FF GY		B		EOL
	PLPQ3-313-FF RD		B		C
	PLPQ3-313-FF YW		B		C
	PLPQ3-375		B		C
	PLPQ3-375 BE		B		C
	PLPQ3-375 BK		B		C
	PLPQ3-375 GN		B		C
	PLPQ3-375 GY		B		EOL
	PLPQ3-375 RD		B		C
	PLPQ3-375 YW		B		C
	PLPQ3-375-FF		B		C
	PLPQ3-375-FF BE		B		C
	PLPQ3-375-FF BK		B		C
	PLPQ3-375-FF GN		B		C
	PLPQ3-375-FF GY		B		EOL
	PLPQ3-375-FF RD		B		C
	PLPQ3-375-FF YW		B		C
	PLPQ3-3MM		B		C
	PLPQ3-3MM BE		B		C
	PLPQ3-3MM BK		B		C
	PLPQ3-3MM GN		B		C
	PLPQ3-3MM GY		B		EOL
	PLPQ3-3MM RD		B		C
	PLPQ3-3MM YW		B		C
	PLPQ3-3MM-FF		B		C
	PLPQ3-3MM-FF BE		B		C
	PLPQ3-3MM-FF BK		B		C
	PLPQ3-3MM-FF GN		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ3-3MM-FF GY	Old Rev.	B	New Rev.	EOL
	PLPQ3-3MM-FF RD		B		C
	PLPQ3-3MM-FF YW		B		C
	PLPQ3-4MM		B		C
	PLPQ3-4MM BE		B		C
	PLPQ3-4MM BK		B		C
	PLPQ3-4MM GN		B		C
	PLPQ3-4MM GY		B		EOL
	PLPQ3-4MM RD		B		C
	PLPQ3-4MM YW		B		C
	PLPQ3-4MM-FF		B		C
	PLPQ3-4MM-FF BE		B		C
	PLPQ3-4MM-FF BK		B		C
	PLPQ3-4MM-FF GN		B		C
	PLPQ3-4MM-FF GY		B		EOL
	PLPQ3-4MM-FF RD		B		C
	PLPQ3-4MM-FF YW		B		C
	PLPQ3-500		B		C
	PLPQ3-500 BE		B		C
	PLPQ3-500 BK		B		C
	PLPQ3-500 GN		B		C
	PLPQ3-500 GY		B		EOL
	PLPQ3-500 RD		B		C
	PLPQ3-500 YW		B		C
	PLPQ3-500-FF		B		C
	PLPQ3-500-FF BE		B		C
	PLPQ3-500-FF BK		B		C
	PLPQ3-500-FF GN		B		C
	PLPQ3-500-FF GY		B		EOL

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ3-500-FF RD	Old Rev.	B	New Rev.	C
	PLPQ3-500-FF YW		B		C
	PLPQ3-5MM		B		C
	PLPQ3-5MM BE		B		C
	PLPQ3-5MM BK		B		C
	PLPQ3-5MM GN		B		C
	PLPQ3-5MM GY		B		EOL
	PLPQ3-5MM RD		B		C
	PLPQ3-5MM YW		B		C
	PLPQ3-5MM-FF		B		C
	PLPQ3-5MM-FF BE		B		C
	PLPQ3-5MM-FF BK		B		C
	PLPQ3-5MM-FF GN		B		C
	PLPQ3-5MM-FF GY		B		EOL
	PLPQ3-5MM-FF RD		B		C
	PLPQ3-5MM-FF YW		B		C
	PLPQ3-6MM		B		C
	PLPQ3-6MM BE		B		C
	PLPQ3-6MM BK		B		C
	PLPQ3-6MM GN		B		C
	PLPQ3-6MM GY		B		EOL
	PLPQ3-6MM RD		B		C
	PLPQ3-6MM YW		B		C
	PLPQ3-6MM-FF		B		C
	PLPQ3-6MM-FF BE		B		C
	PLPQ3-6MM-FF BK		B		C
	PLPQ3-6MM-FF GN		B		C
	PLPQ3-6MM-FF GY		B		EOL
	PLPQ3-6MM-FF RD		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ3-6MM-FF YW	Old Rev.	B	New Rev.	C
	PLPQ3-7MM		B		C
	PLPQ3-7MM BE		B		C
	PLPQ3-7MM BK		B		C
	PLPQ3-7MM GN		B		C
	PLPQ3-7MM GY		B		EOL
	PLPQ3-7MM RD		B		C
	PLPQ3-7MM YW		B		C
	PLPQ3-7MM-FF		B		C
	PLPQ3-7MM-FF BE		B		C
	PLPQ3-7MM-FF BK		B		C
	PLPQ3-7MM-FF GN		B		C
	PLPQ3-7MM-FF GY		B		EOL
	PLPQ3-7MM-FF RD		B		C
	PLPQ3-7MM-FF YW		B		C
	PLPQ3-8MM		B		C
	PLPQ3-8MM BE		B		C
	PLPQ3-8MM BK		B		C
	PLPQ3-8MM GN		B		C
	PLPQ3-8MM GY		B		EOL
	PLPQ3-8MM RD		B		C
	PLPQ3-8MM YW		B		C
	PLPQ3-8MM-FF		B		C
	PLPQ3-8MM-FF BE		B		C
	PLPQ3-8MM-FF BK		B		C
	PLPQ3-8MM-FF GN		B		C
	PLPQ3-8MM-FF GY		B		EOL
	PLPQ3-8MM-FF RD		B		C
	PLPQ3-8MM-FF YW		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1134

Issue Date: 8/5/2026

Parts Affected	PLPQ3-9MM	Old Rev.	B	New Rev.	C
	PLPQ3-9MM BE		B		C
	PLPQ3-9MM BK		B		C
	PLPQ3-9MM GN		B		C
	PLPQ3-9MM GY		B		EOL
	PLPQ3-9MM RD		B		C
	PLPQ3-9MM YW		B		C
	PLPQ3-9MM-FF		B		C
	PLPQ3-9MM-FF BE		B		C
	PLPQ3-9MM-FF BK		B		C
	PLPQ3-9MM-FF GN		B		C
	PLPQ3-9MM-FF GY		B		EOL
	PLPQ3-9MM-FF RD		B		C
	PLPQ3-9MM-FF YW		B		C

Change Will Affect:

This change will affect the product specifications.

Description of Change:

The gray color option has been removed from the PLPQ series product offerings.

Effective Date of Change: August 5, 2026

Reason for Change: As part of our ongoing efforts to streamline our product offerings and improve manufacturing efficiency, the dyed gray color option is no longer available.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122