

**PA-238182**

## **Product Advisory**

**Issue Date: September 27, 2021**

**Change Type:**

BOM component change only

**Parts Affected:**

Part Number	Bracket	Heatsink
BCM957504-P425G	Yes	Yes
BCM957508-P2100G	No	Yes

**Description and Extent of Change:**

Bracket update for PCI-SIG compliance. Heatsink modification for additional keep out area near voltage regulator to improve shock and vibe performance. No change to thermal efficiency.

**Reasons for Change:**

Ensures better fitment and physical compatibility with future OEM server designs. Also improves shock and vibe performance.

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

The adapter specification will remain the same. No changes to adapter form, fit, function, reliability and quality.

**Effective Date of Change:**

The effective date of change is October 15, 2021.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements.  
Please return any response as soon as possible, but not to exceed 30 days.

