



PA-250774

Product Advisory

Issue Date: July 15, 2022

Change Type:

BOM component change only. No change to PCB layout.

Description of Change:

Removal of unused capacitors and resistors near NC-SI connector pads

Reason for Change:

Components may interfering with bracket in limited number of server configurations

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The adapter specification will remain the same. No changes to adapter form, fit, function, reliability and quality.

Effective Date of Change:

The BOM change will be implemented as a running change. Product shipments will begin after September 1, 2022.

Parts Affected:

BCM957508-P2100G

BCM957504-P425G

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.