

Product Advisory

Issue Date: December 1, 2022

Change Type:

Packaging update for specific DCSG NIC adapters.

Description and Extent of Change:

The bulk pack count is increasing from ten to twenty per outer carton. The Minimum Order Quantity (MOQ) will change from ten to twenty.

Reasons for Change:

The change is being implemented to further enhance supply continuity.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The adapter specification will remain the same. No changes to adapter form, fit, function, quality and reliability.

Effective Date of Change:

The part number revision will be incremented to track this update. Product shipments will start after January 15, 2023.

Parts Affected:

BRCM Part Number	New Revision Number
BCM95720N2004DC	24
BCM957412N4120DC	19
BCM957414A4141DDT	5
BCM957414N4140C	20
BCM957414N4140DC	18
BCM957414N4140HC	15
BCM957416N4160DC	15
BCM957502-N150FGB	5
BCM957504-N1100FYB	4
BCM957504-N1100FYC	4
BCM957504-N1100GD	7
BCM957504-N1100GI	6
BCM957504-N425DD	6
BCM957504-N425G	29

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.