

## Product Advisory Notice

Issue Date: January 25, 2023

Advisory Type:


Removal of Test Headers

Parts Affected:

| Board    | Bulk SKU    | Kit SKU     | Old Revision | New Revision |
|----------|-------------|-------------|--------------|--------------|
| 9600-16i | 03-50111-00 | 05-50111-00 | 001          | 002          |
| 9600-24i | 03-50111-01 | 05-50111-01 | 001          | 002          |

Description:

At production, test headers used during development and validation should be removed. The test headers on the 9600-24i and 9600-16i host bus adapters were not removed prior to production. These HBAs are being updated to not populate these headers. As part of this same change, the FW will be updated to the latest available version: MR 8.4.



Effect of Change:

There is no change to form, fit, or functionality.

Effective Date of Change:

This change will be implemented as running change starting March 1, 2023.

---

The changes to these Broadcom parts have been reviewed and approved by Broadcom engineers and managers per Broadcom procedure: Change Control and Customer Notification A-5962-6052-80.

Please contact your Broadcom Inc. field sales engineer or Contact Center (<http://www.broadcom.com/contact/>) for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.