

Product Advisory

Issue Date: June 30, 2023

Change Type:

Supply continuity

Parts Affected:

Part Number
BCM957412N4120CI
BCM957412N4120C
BCM957414N4140CI
BCM957414N4140C
BCM957502-N150G
BCM957504-N1100G
BCM957504-N1100GD
BCM957504-N425G
BCM957504-P425G
BCM957508-N2100G

Description and Extent of Change:

Removing corner bonding material around network controller. No other components on PCBA impacted.

Reasons for Change:

The change is being implement to further enhance supply continuity and standardize across the product lines.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The adapter specification will remain the same. No changes to adapter form, fit, function, quality and reliability.

Effective Date of Change:

The update is being implemented as a running change. Product shipments start after September 1, 2023.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.