

PA-267736

## Product Advisory

Issue Date: August 18, 2022

**Change Type:**

Manufacturing improvement

**Parts Affected:**

Part Number
BCM957502-N150G
BCM957504-N1100G
BCM957504-N1100GI
BCM957504-N425G
BCM957508-N1200G
BCM957508-N1200GI
BCM957508-N2100G
BCM957508-N2100GI

**Description of Change:**

New Mylar cover with perforation

**Reason for Change:**

New Mylar cover will improve manufacturability

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

The adapter specification will remain the same. No changes to adapter fit, form, function, quality, or reliability.

**Effective Date of Change:**

The change will be implemented as a running change. Product shipments will begin after November 1, 2023.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.