

PA-271332

Product Advisory

Issue Date: 13-November-2023

Change Description:

Tray changes for BCM54214 & BCM54216

Parts Affected:

BCM54216ECB1IMLG
BCM54216EB1KMLG
BCM54216EB1IMLG
BCM54214EB1KMLG
BCM54214EB1IMLG


Description and Extent of Change:

Change from Ubot UF10101.00821XA to Ubot UB10101.40821XA

Same Pitch: M=11.95, M3=16.00, M1=11.00, M2=14.65

Same Matrix: 8x21

Tray pocket design change:



Reasons for Change:

To support manufacturing flexibility

Effect of Change on Fit, Form, Function, Quality, or Reliability:

No impact to the devices, the device specification will remain the same.
Two trays with same matrix/pitch design.

Effective Date of Change:

Production will begin to implement with Peak tray from end of Apr'24.

Timing of shipment of the changed part will vary by part number depending on customer demand and inventory level.

The tray rev. can be observed thru physical tray.

Qualification Data:

The tray has been qualified and qual data is available upon request.

Software / Firmware Update:

Not applicable.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements.

Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.