

**PCN-262722**

## **Product Change Notice**

**Issue Date: 27-April-2023**

**Change Description:**

Addition of TSMC Fab16 Foundry source

**Parts Affected:**

BCM43692A1IFFBG

BCM43692A1KFFBG

**Description and Extent of Change:**

Addition of TSMC Fab16 Foundry source

**Reasons for Change:**

Adding second source option for supply chain resiliency

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

All electrical specifications and physical characteristics remain within the datasheet limits. Appropriate electrical characterization and reliability qualifications have been performed on representative products to ensure normal parametric distribution, consistent electrical performance, and reliability.

**Effective Date of Change:**

Product shipments using this change will begin January 2024

**Qualification Data:**

Qualification data will be available after 09/15/2023

Samples will be available upon request from 07/15/2023

**Software / Firmware Update:**

As with all changes please check with your Broadcom FAE to determine if any software or firmware updates are required as a result of this change.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements.

Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.