

Product Change Notice

Issue Date: 07-July-2026

Change Description:


Termination resistor change.

Parts Affected:

Broadcom Part Number	Part Description
AS20-M42M-B11	20 mm Kits 42 bits MT 5V 4 mm BiSS-C
AS20-M42M-S11	20 mm Kits 42 bits MT 5V 4 mm SSI 2-Wire

Description and Extent of Change:

Table 1 : Change Descriptions

Current part	New part
 R10 : 220 Ω	 R10 : 120 Ω

Reasons for Change:

Replacing the 220 Ω termination resistor with 120 Ω to provides proper impedance matching to improve communication stability.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no impact on product Form, Fit, Function and performance at the product level. No impact on quality and reliability.

Effective Date of Change:

Product shipment using this change effectively around October 2026.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.