



Customer Product/Process Change Notification

PCN # **136056**

Issued Date: _____

Issued By: Cheryll Santiago

Author: _____

Change affects whole product family?

NO

Part #'s affected (See attached if entire product family is affected)

SEE AFFECTED PART NUMBERS TAB

Description of Change:

Parts are obsoleted due to No Demand / Low Demand over the past 3 years.

Reason for Change:

Parts are obsoleted due to No Demand / Low Demand over the past 3 years.

Properties of Old vs. Changed Product:

Disposition of Old Product:

Deplete on hand stock

Expected Implementation Date: 7/1/2026

Customer Feedback Expected by: N/A

Additional Comments: (Include Potential Risks if Appropriate)

Dialight can offer alternate part numbers for the discontinued parts.

Supporting Qualification Data:

Attached as necessary

Dialight North America

1501 Route 34 South | Farmingdale | New Jersey | 07727 | USA | Tel: 732-919-3119 | www.dialight.com

Affected Part Numbers

PCN # 136056

Part Numbers Affected by the change.

<u>Part Number</u>	<u>Part Number</u>	<u>Part Number</u>
5973007507F	5218396F	HLMP1385101F
5973027507F	5501510804F	HLMP1402101F
5973207507F	5503509805F	HLMP1640101F
5973507507F	5513407F	HLMP1700101F
5973607507F	5530717F	HLMP1790101F
5973907507F	5530777200F	HLMP1300104F
5973005507F	5610004807F	HLMP1301102F
5973035507F	5610006801F	HLMP1301103F
5973045507F	5610006803F	HLMP1301108F
5973205507F	5610008801F	HLMP1302102F
5973405507F	5610018801F	HLMP1302104F
5973505507F	5610025801F	HLMP1302107F
5973006507F	5610043802F	HLMP1321104F
5973036507F	5640005807F	HLMP1340104F
5973206507F	5640012805F	HLMP1385108F
5973408507F	5640012806F	HLMP1401102F
5973409507F	5642210812F	HLMP1401104F
5973506507F	5640710777F	HLMP1402104F
5973316507F	5640710802F	HLMP1521104F
5975006507F	5660506F	HLMP1600104F
5975036507F	5670001802F	HLMP1620104F
5975206507F	5680004862F	HLMP1700102F
5975316507F	5680004867F	HLMP1700104F
5975326507F	5680004869F	HLMP1700105F
5975406507F	5680004871F	HLMP1700106F
5975506507F	5680004874F	HLMP1700107F
5975606507F	5680004875F	HLMP1700108F
5975906507F	5680004876F	HLMP1719102F
5972203507F	5680008801F	HLMP1719104F
5975606507F	5680008802F	HLMP1790102F
5973045507F	5680008804F	HLMP1790103F
5976325607F	5680008806F	HLMP1790104F
5973905607F	5680008807F	HLMP1790105F
5973605607F	5680008808F	HLMP1790108F
5973001607F	5680008809F	HLMPK101104F
5973041607F	5680012801F	
5973401607F	5680012804F	
5973321607F	5680012805F	
5973601607F	5680012807F	
5972771607F	5680016802F	
5973006607F	5680016803F	
5973007607F	5680016804F	
5973326607F	5680016812F	