


Product/Process Change Notifications



PCN - 15 096-R.2

Release Date: September 25 2015

Product Name:	DDR4 TH/SMT/PF		
	DDR4 TH/SMT/PF		
Product Manager:	Bonnie Liu		
Subject:	Notification of Change with Immediate Effectivity		
Distribution:	General		
Type of Change:	Design Change		
Change Description:	Change the latch rib length from 2.5mm to 1.25mm, change the bump straight line length from 0.97mm to 0.47mm. Add a chamfer on housing tower slot, the bottom of the slot retains the same size. 		
Reason for Change:	To reduce the latch overstress force on housing tower. By Revision 2 - Part Numbers starting with "10129206-" are removed from the affected list (9Nos) which are unaffected by this change and were added by mistake.		
Affected Parts:	10124632, 10129040, 10130419, 10124677, 10133530, 10135356, 10124806		
Effective Date of Change:	October 15, 2015		
Last Time Buy Date:	NA		
Last Disty Return Date:	NA		
Last Time Shipment Date	NA		
Datasheet Attached?	NA		
Qual/Test Data Attached?	NA		
Samples Availability Date:	September	28	2015
Available Alternatives?	N/A		
Questions?	Contact your local FCI Representative, or Product Manager		
	Bonnie Liu / Product Manager		
	+86 769 88669459/ Bonnie.liu@fci.com		

Note:

Customer shall intimate the product Manager any Concern regarding the PCN within 3 weeks of the release date.
 PCN is considered approved by the customer if no communication is received within 3 weeks