



**LEMO**®

## PRODUCT UPDATE


LEMO USA, Inc.  
635 Park Court  
P.O. Box 2408  
Rohnert Park, CA 94927-2408

Main (707) 578-8811  
Toll Free (800) 444-5366  
Fax (707) 578-0869  
Email [info@lemousa.com](mailto:info@lemousa.com)


Number: #132  
By: Applications Engineering Dept.  
Date: May 28, 2014

### 3S Collet Slot Modification



The design for ALL 3S C-Type Collets have been updated to have 4 slots rather than 6. The bevel shape surrounding the notch will also be slightly different. The collet part number will change to have a "T" suffix. The part numbers affected with this change are: FFA.3S.7\_\_.CN Below is an example of the new updated collet vs. the older version:



**FFA.3S.742.CN**



**FFA.3S.742.CNT**



If you have any questions or concerns regarding this change, please contact Customer Service or Applications Engineering at 1-800-444-5366 or email: [info@lemousa.com](mailto:info@lemousa.com)

Thank you for your continued support of LEMO products!